

HUMACAO

DR HERMENEGILDO ORTIZ QUINONES (X63) 1 SE UTC-4 N18°08.28' W65°48.04' PUERTO RICO-VIRGIN ISLANDS

35 B NOTAM FILE TJSJ

RWY 10-28: H2458X60 (ASPH) S-20 MIRL 0.4% up W

RWY 10: Tree.

AIRPORT REMARKS: Attended 1130-2000Z. Parachute Jumping. Birds activity on and in/ovf arpt. Skydiving, ultralights opns on arpt. Rising terrain in/ovf arpt. Cattle 500' from thld Rwy 28, occasionally on rwy. Loose stones and gravel on rwy and txy. Ldg fee.

AIRPORT MANAGER: 787-852-8188

COMMUNICATIONS: CTAF 122.8

CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665

COMM/NAV/WEATHER REMARKS: Two-way radio communication required for acft and vehicles excp by prior request; Call 787-852-8188.

ISLA DE CULEBRA

BENJAMIN RIVERA NORIEGA (CPX)(TJCP) 1 N UTC-4 N18°18.78' W65°18.23' PUERTO RICO-VIRGIN ISLANDS

49 B LRA NOTAM FILE TJSJ

RWY 13-31: H2600X60 (ASPH) S-12 MIRL 1.4% up NW

RWY 13: Hill.

RWY 31: Fence.

SERVICE: LGT Rtg bcn OTS indef. Rwy 13-31 MIRL-several lts OTS indef.

AIRPORT REMARKS: Unatndd SS-SR. Emergs only. Opns between SS-SR will be an own risk. Birds on and in/ovf rwy. Rapidly rising terrain NW. Low alt maneuvering rqrtd for final alignment to rwy, variable degrees of turbulence may be expd. Acft departing arpt northbound be alert for t/c descending on final for Charlotte Amalie St. Thomas, Cyril E. King (STT). Ldg Rwy 13 only (exc for adverse wx cond). Apch from NW thru Bahia Flamenco hdg 172°. Fly thru Laguna Del Flamenco until aprx parallel to highway in pass alter hdg to 153°, left turn to final. Rapidly rising terrain NW. Rwy, twy pavement cracking, loose stones. Ldg fee for all acft.

AIRPORT MANAGER: 787-742-0022

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665

ISLA DE VIEQUES

ANTONIO RIVERA RODRIGUEZ (VQS)(TJVQ) 3 SW UTC-4 N18°08.09' W65°29.62' PUERTO RICO-VIRGIN ISLANDS

49 B LRA NOTAM FILE TJSJ

RWY 09-27: H4301X75 (ASPH) S-20, D-40 MIRL 0.5% up SW

RWY 09: PAPI(P4L)—GA 3.0° TCH 46'. Thld dsplcd 896'. Trees.

RWY 27: Road. Rgt t/c.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 09: TORA-4301 TODA-4301 ASDA-4301 LDA-3405

RWY 27: TORA-4301 TODA-4301 ASDA-4301 LDA-3405

SERVICE: LGT Rtg bcn OTS indef.

AIRPORT REMARKS: Attended 1000-2200Z. VFR opns only. Rising terrain south. Acft not visible from opposite rwy end. Clsd to sked air carrier oper with more than 9 psgr seats and unsked air carrier oper with more than 30 psgr seats. PPR for other B-III acft and max wingspan of 88.75 ft, ctc AMGR. AMGR aftr hrs ph 787-439-5941. Const of twy south of Rwy 09-27. Rwy 09 day landing length 4094, night landing 3405. Rwy 09 dsplcd thld marked at 207 ft. No thld lights. Ldg fee for all acft.

AIRPORT MANAGER: 787-729-8715

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ SAN JUAN CERAP 128.65

CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at

787-253-8664/8665

RADIO AIDS TO NAVIGATION: NOTAM FILE TIST.

ST THOMAS (L) (L) VOR/DME 108.6 STT Chan 23 N18°21.35' W65°01.47' 254° 29.9 NM to fld. 679/10W.

VOR unusable:

060°-070° byd 35 NM blo 2,200'

085°-115° byd 16 NM blo 7,500'

160°-175° byd 35 NM blo 2,500'

255°-265° byd 25 NM

290°-305° byd 15 NM

DME unusable:

085°-115° byd 30 NM blo 7,500'

COMM/NAV/WEATHER REMARKS: UNICOM monitored during attendance hrs.

