

DURANGO

ANIMAS AIR PARK (ØØC) 4 S UTC-7(-6DT) N37°12.19' W107°52.15'

DENVER
H-4K, L-8I, 9E

6684 NOTAM FILE DEN

RWY 01-19: H5010X50 (ASPH) MIRL 1.1% up N

RWY 01: Rgt tfc.

RWY 19: Brush.

SERVICE: S4 FUEL 100LL, JET A OX1 LGT Actvt MIRL Rwy

01-19-122.9. Rwy 01-19 thr lgts N end 162 ft fm pavement end.

AIRPORT REMARKS: Attended dalgt hrs. CTN: Hel hosp ops 2.4 NM NE. Rwy 01-19 -1 to -2 ft drainage ditches 35 ft W and 30 ft E alg cntrln; +4 ft fence 87 ft W alg cntrln; +10 ft road 105 ft W alg cntrln. Rwy 01, 200 ft dropoff 120 ft fm and parallel thr; +15 ft trees 1817 ft fm thr 105 ft L of cntrln.

AIRPORT MANAGER: 970-247-4632

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DRO.

DURANGO (VL) (DH) VOR/DME 116.55 DRO Chan 112(Y)

N37°09.20' W107°44.98' 284° 6.5 NM to fld. 6662/14E.

VOR unusable:

004°-014° byd 40 NM blo 16,500'

004°-014° byd 50 NM

015°-070° byd 40 NM

131°-190° byd 40 NM

220°-225° byd 40 NM

250°-003° byd 40 NM

290°-310° byd 15 NM blo 17,000'

DME unusable:

070°-090° byd 30 NM blo 12,500'

140°-185° byd 25 NM blo 13,000'

290°-310° byd 15 NM blo 17,000'

