



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES  
 READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

NOTE: Due to distance of tower from transient ramp,  
 ATC unable to provide visual guidance or positioning  
 of aircraft. USE CAUTION.

ATIS  
 133.15  
 FLINT TOWER \*  
 126.3 257.9  
 GND CON  
 121.9  
 CLNC DEL  
 121.75  
**D**



EC-1, 05 SEP 2024 to 03 OCT 2024

EC-1, 05 SEP 2024 to 03 OCT 2024