

24249

ILS Y or LOC Y RWY 26L
HARRY REID INTL (LAS)

MISSED APPROACH: Climb to 3200 then climbing right turn to 6000 heading 080° and on BLD R-286 to BLD VORTAC and hold, continue climb-in-hold to 6000.

[illegible]

3200 6000 BLD R-286 BLD VGSB and ILS glidepath not coincident (VGSB Angle 3.00/TCH 84) BERBN

hdg 080°

RELIN 3800 HUXAR 5000 KODSE 5800 BISHP 7000 8000

I-RLE 1.9 I-RLE 3.1 I-RLE 7.2 I-RLE 11.8

1.2 NM 4.1 NM 4.6 NM 2.6 2.7 1.4 3 NM

259° 317° 020° 079°

GS 3.00° TCH 60

ELEV 2181

D

TDZE 26L 2069

TDZE 26R 2067

18-19L 14515 X 150 1.1% DOWN

26L-26R 10526 X 150 1.2% DOWN

TWR 2433

259°

MIRA Rwy 18-19L

REIL Rwys 1R, 8R, 19L and 19R

HIRL Rwys 1L-19R, 8L-26R and 8R-26L

HARRY REID INTL (LAS)
ILS Y or LOC Y RWY 26L

SW-4, 05 SEP 2024 to 03 OCT 2024