ARRIVAL ROUTE DESCRIPTION

BUKYY TRANSITION (BUKYY.WAALK2): HYTRA TRANSITION (HYTRA.WAALK2): ZJAAY TRANSITION (ZJAAY.WAALK2):

<u>Landing all airports:</u> From WAALK on track 039° to cross CSINO at 7000, then on track 039° to HOGGS, then on track 052° to cross PANZE at 5000, then on track 030° to cross FALON at 5000. Then on track 030°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

After FALON, proceed direct CYN at 5000 feet, hold at CYN as published, descend in holding from 5000 to 3000 feet.