

BELUGA (BLG)(PABG) PVT UTC-9(-8DT) N61°10.38' W151°02.72'

87 NOTAM FILE Not insp.

RWY 01-19: 5002X100 (GRVL) MIRL

RWY 01: Trees.

RWY 19: Trees.

RWY 09-27: 2505X60 (GRVL) MIRL 0.5% up W

SERVICE: LGT ACTVT MIRL Rwy 01-19 and Rwy 09-27—CTAF.

AIRPORT REMARKS: Attended continuously. Wildlife on and invof airport.

Rwy 09-27 not mntnd in winter. Gtr than 20,000 lb and all ldg ops

PPR—907-263-3930/907-263-3910. Rws not visible by psnl.

Unctld vehicle ops on road alg E side of rws. W side of twy shoulder

NA byd rwy edge lights. Shoulder area on W and N side of rws soggy.

Rwy 19 first 200 ft soft and unstable. Road Xs adj to N end Rwy 19.

Brush hinders vehicles fm seeing arr on apch end Rwy 19. Located 8

SM NE Tyonek.

AIRPORT MANAGER: 907-777-8300

COMMUNICATIONS: CTAF/UNICOM 122.7

RADIO AIDS TO NAVIGATION: NOTAM FILE ANC.

ANCHORAGE (H) VOR/DME 113.15 TED Chan 78(Y)

N61°10.07' W149°57.61' 253° 31.5 NM to fld. 92/18E.

VOR unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

DME unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

196°-206° byd 25 NM blo 3,500'

206°-211° byd 25 NM blo 4,000'

211°-221° byd 25 NM blo 3,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

HELIPAD H1: H60X60 (CONC)

ANCHORAGE
H-1B, 2K, L-1A, 3D, 4F

