HAVANA RGNL (9IØ) 5 SE UTC-6(-5DT) N40°13.36' W90°01.37' 488 B NOTAM FILE IKK RWY 09-27: 2235X100 (TURF) MIRL SERVICE: FUE 100LL AIRPORT REMARKS: Attended irregularly. Self svc fuel avbl 24 hrs. AIRPORT MANAGER: 309-543-9006 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc St Louis Apch 314-890-1017. HIGHLAND—WINET (HØ7) 3 NE UTC-6(-5DT) N38°46.76' W89°38.43' 537 NOTAM FILE STL RWY 18-36: 2200X100 (TURF) RWY 18: ThId dsplcd 180'. RWY 36: Thid dsplcd 180'. RUY 18: Thid dsplcd 180'. RUY 19: Thid 30'.<	CHICAGO
 537 NOTAM FILE STL RWY 18-36: 2200X100 (TURF) RWY 18: Thid dspicd 180'. RWY 36: Thid dspicd 354'. Road. Rgt tfc. AIRPORT REMARKS: Unattended. Extensive glider ops along W side of rwy; gliders fly opposite pattern to powered act 18–36 dspicd thids marked with white in-ground markings, also both sides of rwy marked with white in-ground To assure firm turf; do not taxi S of above ground fuel tank. Administration bldg can be accessed by pushing nu 	
AIRPORT MANAGER: 618-977-3857 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc St Louis Apch at 314-890-1017.	d stripes.
 HINCKLEY (ØC2) 3 W UTC-6(-5DT) N41°46.25' W88°42.20' 760 NOTAM FILE IKK RWY 09-27: 2640X100 (TURF) AIRPORT REMARKS: Attended irregularly. Glider ops surface-17,500'. Rwy 09-27 not plowed; use at own risk. Arpt unusable under very wet conditions. AIRPORT MANAGER: 316-213-7093 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Chicago Apch at 847-289-0926. 	CHICAGO may be
HUSKK N39°46.39´W89°45.59´ NOTAM FILE SPI. NDB (MHW/LOM) 382 SP 043° 5.7 NM to Abraham Lincoln Capital. 602/1W.	ST. LOUIS

INGERSOLL (See CANTON on page 36)