
MC CLUSKY MUNI (7G2) 2 SW UTC-6(-5DT) N47°27.72' W100°29.23' TWIN CITIES
 1900 NOTAM FILE GFK
RWY 13-31: 3136X80 (TURF) 0.3% up NW
AIRPORT REMARKS: Unattended. Cfm ireg snow removal & winter conds with amgr prior to use. Snow removal emerg only call 701-220-4365. Rwy 13-31 has nmrs grass clumps.
AIRPORT MANAGER: 701-220-4365
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

MC VILLE MUNI (8M6) 1 NW UTC-6(-5DT) N47°46.22' W98°11.09' TWIN CITIES
 1473 NOTAM FILE GFK
RWY 18-36: 2500X90 (TURF)
RWY 18: Road.
RWY 36: Road.
RWY 13-31: 2277X100 (TURF) LIRL
RWY 13: Road.
RWY 31: Bldg.
SERVICE: LGT ACTIVATE LIRL Rwy 13-31 —CTAF.
AIRPORT REMARKS: Unattended. Call arpt manager to confirm snow removal 701-270-2820. Rwy 13-31 200' turf stopway on northwest end and 500' turf stopway on southeast end. Rwy 13-31 turf surface rolling. Rwy 36 has multiple 110' bldgs 1400' fm thld; L and R of cntrln. Rwy 36 has 40' trees 175' fm thld; 110' L of cntrln. Rwy 31 has 40' trees 720' fm thld; L and R of cntrln.
AIRPORT MANAGER: (701) 739-1345
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

MERCER CO RGNL (See HAZEN on page 342)

MILNOR MUNI (4R6) 1 E UTC-6(-5DT) N46°15.50' W97°26.27' TWIN CITIES
 1091 NOTAM FILE GFK
RWY 08-26: 2210X90 (TURF)
RWY 08: Road.
AIRPORT REMARKS: Unattended. Deer and birds on or invof arpt. Confirm arpt condition prior to ldg due to irregular snow removal, phone request only 701-680-1001. Rwy 08-26 crosswind turbulence due to close proximity tree growth, additionally, tress to north and south, windsocks and buildings to the north of rwy penetrate 7:1 transitional surface. Rwy 08-26 has 250' turf stopway west end.
AIRPORT MANAGER: 701-680-1001
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.
