

PIER 7 HELIPORT (See BALTIMORE on page 94)

POTOMAC AIRFIELD (See FRIENDLY on page 101)

RIDGELY

GOODEN AIRPARK (RJD)(KRJD) 2 NE UTC-5(-4DT) N38°58.21' W75°51.98'

WASHINGTON
L-34F, 361, A
IAP

64 B NOTAM FILE DCA

RWY 12-30: H3214X50 (ASPH) S-28, D-39 LIRL

RWY 12: REIL. P-line.

RWY 30: REIL. Trees. Rgt t/c.

SERVICE: S4 LGT Actvt aprt beacon—CTAF. Actvt REIL Rwy 12 & 30; LIRL Rwy 12-30—CTAF.

AIRPORT REMARKS: Unattended. Birds, deer and wildlife on and in/ov arpt. Unlimited vehicle access to acft movement areas. Turf areas adjacent to acft movement areas soft when wet. Twy/Apn pavements are failing with loose aggregate and alligator cracking. Rwy 12-30 thld bars and rwy numbers are half size. Rwy 12 and 30 mkg condition faded, crack seal thru mrkgs.

AIRPORT MANAGER: 302-270-2227

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **POTOMAC APP/DEP CON** 124.55

DOVER APP/DEP CON 132.425 (Rwy 30)

CLEARANCE DELIVERY PHONE: For CD ctc Dover Apch at 302-677-3940.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

SMYRNA (L) (L) VORTACW 111.4 ENO Chan 51 N39°13.90'

W75°30.96' 235° 22.7 NM to fld. 15/9W.

TACAN AZIMUTH unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'

VOR unusable:


159°-169° blo 3,000 . 325-335 byd 15NM blo 4,900'

DME unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'

COMM/NAV/WEATHER REMARKS: UNICOM unmon.



ST MARY'S CO RGNL (See LEONARDTOWN on page 106)

SALISBURY

BENNETT (1N5) 4 NW UTC-5(-4DT) N38°24.77' W75°37.02'

WASHINGTON

46 B NOTAM FILE DCA

RWY 17-35: 3171X95 (TURF) LIRL

RWY 17: APAP(PNIL)—GA 4.0° TCH 23'. Thld dspld 240'. Road.

RWY 35: APAP(PNIL)—GA 5.0°. Thld dspld 941'. Road.

RWY 08-26: 2302X95 (TURF)

RWY 08: Thld dspld 800'. Road.

RWY 26: Thld dspld 300'. Road.

SERVICE: LGT Dusk-0400Z‡. Actvt LIRL Rwy 17-35 and bcn—CTAF.

AIRPORT REMARKS: Attended dawn-dusk. Ultralight act on and in/ov arpt. Birds and wildlife on and in/ov arpt. +375 ft lgtd ant 3200 ft L of Rwy 35 thr on L downwind. Rwy 08 and Rwy 26 dthr mkd with 3 orange cones. Rwy 17 and Rwy 35 thr and dthr mkd with lgts and cones. Rwy 17-35 +60 ft trees mid-point both sides of rwy. +70' trees mid-point both sides rwy 17-35.

AIRPORT MANAGER: (443) 880-7428

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **PATUXENT APP/DEP CON** 127.95 (1200-0400Z‡ Mon-Sun. Other times by NOTAM) other times ctc

Ⓡ **POTOMAC APP/DEP CON** 127.2

CLEARANCE DELIVERY PHONE: For CD ctc Patuxent Apch at 301-342-3740, when Patuxent Apch is clsd ctc Potomac Apch at 866-640-4124.