VERMONT

WARREN-SUGARBUSH (ØB7) 2 E UTC-5(-4DT) N44°07.04´W 1470 NOTAM FILF BTV	V72°49.62′ MONTREA
 RWY 04-22: H2575X30 (ASPH) S-8.5 0.5% up SW RWY 04: Trees. Rgt tfc. RWY 22: Trees. SERVICE: FUEL 100LL AIRPORT REMARKS: Attended May-Oct 1400–2300Z‡. Arpt CLOSED Nov-Ap Extensive glider activity on arpt sfc to 18,000' dalgt hrs. Occasional ar activity; check NOTAMs. No line of sight between rwy ends. Touch and for taxi, tkfs and Idgs without first checking UNICOM or management fi AIRPORT MANAGER: 802-496-2290 COMMUNICATIONS: CTAF/UNICOM 123.0 CLEARANCE DELIVERY PHONE: For CD ctc Burlington Apch at 802-657-4413, 603-879-6859. 	erobatic activity, arpt may be CLOSED during this go ldgs not permitted. Grass areas not authorized or fld conditions.
VEST DOVER DEERFIELD VALLEY RGNL (4V8) 1 SW UTC-5(-4DT) N42°55.6 1953 NOTAM FILE BTV RWY 01-19: H2650X75 (ASPH) MIRL(NSTD) RWY 01: Trees. RWY 19: Trees. SERVICE: LGT Rwy 01-19 MIRL, NSTD alnmt. AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ldg fee. AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ldg fee. AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ldg fee. AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ldg fee. AIRPORT REMARKS: 040-0775 COMMUNICATIONS: CTAF/UNICOM 122.8 (®) BOSTON CENTER APP/DEP CON 123.75 CLEARANCE DELIVERY PHONE: For CD cto Boston ARTCC at 603-879-6859. RADIO AIDS TO NAVIGATION: NOTAM FILE BTV. CAMBRIDGE (L) (L) VORW/DME 115.0 CAM Chan 97 N42°59.66' W73°20.64' 115° 21.5 NM to fid. 1490/14W. DME unusable: 040°-130° blo 9,000' VOR unusable: 128°-144° 161°-182° 195°-205°	3' W72°51.94' NEW YOR L-326,33 Golf Course 61 G G G G G G G G G G G G G G G G G G G

WILLIAM H MORSE STATE (See BENNINGTON on page 323)