86

THOMAS CREEK (2U8) 31 N UTC-7(-6DT) N44°43.40′ W115°00.24′

GREAT FALLS

4415 NOTAM FILE BOI

RWY 03-21: 2100X75 (TURF-DIRT) 2.5% up SW

RWY 03: Hill.

RWY 21: Tree.

AIRPORT REMARKS: Unattended. No winter maint. Recommend ldg Rwy 21, tkf Rwy 03, go arounds extremely difficult. Rwy 03 first 400' is dog leg with a heading of 360°. Acft loading and unloading at the south end of Rwy 21. Considerable air taxi ops mid to late summer. Rwy 03-21 usable width may vary from 75' to 100'. Arpt is lctd on plateau 100-150'

AIRPORT MANAGER: 208-334-8775 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

STANLEY N44°10.19′ W114°55.87′

SALT LAKE CITY L-11C

RCO 122.6 (BOISF RADIO)

STRIK N42°28.72′ W114°21.27′ NOTAM FILE TWF.

SALT LAKE CITY

NDB (LOMW) 389 TW 259° 5.9 NM to Joslin Fld/Magic Valley Rgnl. 4066/13E.

L-11C

TANGLEFOOT SPB (See CAVANAUGH BAY on page 44)

THATCHER

WERANCH (ØID) 3 NW N42°26.89′ W111°46.65′ SALT LAKE CITY

5075 NOTAM FILE HUF RWY 17-35: 1350X48 (GRVL)

RWY 17: Rgt tfc.

RWY 35: Rgt tfc.

AIRPORT REMARKS: Unattnd. Rwy 17-35 lctd on a plateau; sharp drop off near both rwy ends. No winter maint; use at own risk.

AIRPORT MANAGER: 801 440 6204 COMMUNICATIONS: CTAF 122.9

THOMAS CREEK (See STANLEY on page 86)

THREE CREEK

MURPHY HOT SPRINGS (3UØ) 9 W UTC-7(-6DT) N42°01.41′ W115°20.13′

SALT LAKE CITY

5829 NOTAM FILE BOI

RWY 01-19: 5250X120 (TURF) 1.2% up S

RWY 01: Fence. RWY 19: Fence.

AIRPORT REMARKS: Unattended. No telephone avbl at arpt. No winter maint. No line of sight between rwy ends. Recommend land Rwy 19 and depart Rwy 01 when wind conditions permit. Rwy soft in spring and when wet. Rwy 01-19 edges and thids marked with white rock.

AIRPORT MANAGER: 208-334-8775 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

TWIN BRIDGES (See KETCHUM on page 62)