


**PORT LAVACA****CALHOUN CO** (PKV)(KPKV) 3 NW UTC-6(-5DT) N28°39.20' W96°40.96'**HOUSTON**H-7C, L-20I, 21A, GOMW  
IAF

32 B NOTAM FILE PKV

**RWY 14-32:** H5004X75 (ASPH) S-26 MIRL**RWY 14:** PAPI(P2L)—GA 3.0° TCH 45'. Road.**RWY 32:** PAPI(P2L)—GA 3.0° TCH 45'. Road. Rgt tfc.**RWY 05-23:** 2432X60 (TURF)**RWY 05:** Tree.**RWY 23:** Thld displcd 428'.**SERVICE:** S4 FUEL 100LL, JETA LGT ACTVT MIRL Rwy 14-32—CTAF.**AIRPORT REMARKS:** Attended 1400-2300Z†. 100LL and Jet A avbl 24 hrs self serve. Jet A also avbl by truck. RC model acft opr at Rwy 05 end.**AIRPORT MANAGER:** 361-552-1228**WEATHER DATA SOURCES:** AWOS-3 118.275 (361) 552-3060.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **HOUSTON CENTER APP/DEP CON** 135.05**CLEARANCE DELIVERY PHONE:** For CD ctc Houston ARTCC at 281-230-5622.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PSX.**PALACIOS (VH) (H) VORTACW** 117.3 PSX Chan 120 N28°45.87'

W96°18.37' 244° 20.9 NM to fld. 16/8E.

**PORT MANSFIELD****CHARLES R JOHNSON** (TØ5) 1 NW UTC-6(-5DT) N26°33.61' W97°26.36'**BROWNSVILLE**

L-20H, 21A

10 B NOTAM FILE SJT

**RWY 12-30:** H3200X50 (ASPH) S-21 MIRL**RWY 12:** P-line.**RWY 30:** P-line.**SERVICE:** LGT MIRL Rwy 12-30 preset low intst; to increase intst ACTVT—CTAF.**AIRPORT REMARKS:** Unattended. Harbor superintendent's ofc attended 1400-2250Z†. Deer & birds on & invof arpt. Rwy 12 and Rwy 30 rwy mks discolored. Fee for ovnght tie down.**AIRPORT MANAGER:** 956-944-2325**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HRL.**HARLINGEN (L) (L) VORW/DME** 113.65 HRL Chan 83(Y) N26°13.75' W97°39.14' 025° 22.9 NM to fld. 32/5E.**PORTLAND****HUNT** (9R5) 2 NW UTC-6(-5DT) N27°53.20' W97°20.98'**BROWNSVILLE**

40 NOTAM FILE SJT

**RWY 14L-32R:** H2650X20 (ASPH) S-9 0.6% up NW**RWY 14L:** P-line. Rgt tfc.**RWY 32R:** Brush.**RWY 14R-32L:** 1400X60 (TURF-GRVL)**RWY 14R:** Rgt tfc.**NOISE:** Noise abatement procedures in effect. Call arpt manager at 361-643-3950.**AIRPORT REMARKS:** Unattended. Rwy 14R-32L CLOSED indef. Wind turbines N of arpt. Rwy 14L-32R has severe grass encroachment, pot holes, and loose gravel on rwy. Rwy 14R-32L heavy rutting along entire rwy length. Rwy 14L-32R limited line of sight between thlds; southern 600' of rwy drops off approximately 8'. Rwy 32R ground drops off approximately 10' at thld.**AIRPORT MANAGER:** 361-643-3950**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**POSSUM KINGDOM** (See GRAFORD on page 324)