

HATTERAS**BILLY MITCHELL** (HSE)(KHSE) 4 E UTC-5(-4DT) N35°13.97' W75°37.07'**CHARLOTTE**

16 NOTAM FILE HSE

L-35C

RWY 07-25: H3002X75 (ASPH) S-30

IAP

RWY 07: Brush.**RWY 25:** Tree.

AIRPORT REMARKS: Unattended. Arpt CLOSED 30 min after SS until 30 min before SR. All ngt time ops prohibited. Flocks of seagulls on and invof arpt. High speed low-level mil ops invof arpt. Arpt located in Cape Hatteras National Seashore. Maintain 2000' vertical and horizontal distance from seashore beaches. Additional acft parking avbl on mid-field apron. Rwy 07-25 safety area is loose sand and dunes—not suitable for acft. +10-35' sand dunes and scrub trees boths of rwy within ROFA.

AIRPORT MANAGER: 252-475-9000**WEATHER DATA SOURCES:** ASOS 118.375 (252) 995-3646.**COMMUNICATIONS:** CTAF 122.9**HATTERAS RCO** 122.3 (RALEIGH RADIO)Ⓡ **CHERRY POINT APP/DEP CON** 119.75**CLEARANCE DELIVERY PHONE:** For CD ctc Cherry Point Apch at 252-466-5960.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ECG.**ELIZABETH CITY (L) (L) VORW/DME** 115.75 ECG Chan 104(Y)

N36°15.45' W76°10.54' 163° 67.2 NM to fld. 7/7W.

DME unusable:

250°-280° byd 30 NM blo 8,000'

WRIGHT BROTHERS (T) (T) VORW/DME 111.6 RBX Chan 53 N35°55.23' W75°41.82' 183° 41.4 NM to fld.

10/8W. NOTAM FILE MQI. VOR/DME unmonitored 2300-1300Z‡.

VOR unusable:

281°-318° blo 8,000'

319 blo 4,000'

320°-280°

CHERRY POINT (L) TACAN Chan 75 NKT (112.8) N34°54.14' W76°52.49' 081° 65.0 NM to fld.


25/9W. NOTAM FILE RDU.

TACAN AZIMUTH unusable:

052°-060° byd 10 NM blo 3,000'

061°-089° byd 6 NM blo 5,000'

090°-109° byd 10 NM blo 3,000'

**HATTERAS** N35°14.01' W75°37.06'**CHARLOTTE**

RCO 122.3 (RALEIGH RADIO)

L-35C

HENDERSON/OXFORD (See OXFORD on page 336)**HENDERSONVILLE** (ØA7) 2 E UTC-5(-4DT) N35°18.46' W82°25.99'**ATLANTA**

2084 NOTAM FILE RDU

L-25C

RWY 15-33: H3075X40 (ASPH) S-10 RWY LGTS(NSTD)**RWY 15:** Thld dspcld 270'. Trees.**RWY 33:** Thld dspcld 325'. Trees.

SERVICE: S4 LGT Actvt LIRL Rwy 15-33—CTAF. OTS indefly. Rwy 15-33 no end or dspcld thld lgts; lgts 50' from rwy edge south side and 11' from rwy edge north side. OTS indefly daylight opr only.

AIRPORT REMARKS: Attended 1330-2230Z‡. For svc after hrs call 828-693-1897. Acft parked 40' from edge of Rwy 33. Numerous obstructions in apch and primary sfc. Hangar 90' left of Rwy 33. Landing traffic use caution when winds greater than 10 kts. Rwy 15 numbers and rwy markings smaller than standard. Numbers visible but cntrl'n nonexistent. North side of rwy has 60' trees 80' from cntrl'n.

AIRPORT MANAGER: 828-693-1897**COMMUNICATIONS:** CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Asheville Apch at 828-684-7259. When Asheville Apch clsd, for CD ctc Atlanta ARTCC at 770-210-7692.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.**SUGARLOAF MOUNTAIN (L) (L) VORTACW** 112.2 SUG Chan 59 N35°24.39' W82°16.12' 236° 10.0 NM to fld.

3970/2W.

HIATT (See THOMASVILLE on page 354)