

CHARLESTON EXEC (JZI)(KJZI) 6 SW UTC-5(-4DT) N32°42.06' W80°00.20'

19 B NOTAM FILE AND

CHARLOTTE

H-9C, 12G, L-24I

IAP

RWY 09-27: H5350X100 (CONC-GRVD) S-60, D-100 HIRL**RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. Trees.**RWY 27:** REIL. PAPI(P4R)—GA 3.0° TCH 44'. Thld dspld 350'.

Brush.

RWY 04-22: H4313X150 (CONC) S-45, D-56 MIRL**RWY 04:** Tree.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** SR-SS, to actvt and incr instt
 REIL Rwy 09 and 27; HIRL Rwy 09-27; MIRL Rwy 04-22—CTAF.
 SR-SS, PAPI Rwy 09 and 27 opr consly. SS-SR, REIL Rwy 09 and 27;
 PAPI Rwy 09 and 27; HIRL Rwy 09-27 opr consly, to incr instt—CTAF.
 SS-SR, to actvt MIRL Rwy 04-22—CTAF. Supplementary lgtd
 windcones Rwys 04, 22, 09 and 27.

AIRPORT REMARKS: Attended 1100-0300Z†. Deer and birds on and invof
 arpt.

AIRPORT MANAGER: 843-767-7000**WEATHER DATA SOURCES:** AWOS-3 123.775 (843) 559-3123.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **APP/DEP CON** 120.7**CLNC DEL** 119.85**CLEARANCE DELIVERY PHONE:** For CD ctc Charleston Apch at 843-414-2832.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CHS.**(VH) (H) VORTAC** 113.5 CHS Chan 82 N32°53.66'

W80°02.27' 176° 11.7 NM to fld. 39/5W.

VOR unusable:

070°-106° byd 40 NM

106°-116°

116°-146° byd 40 NM

248°-272° byd 40 NM blo 8,000'

TACAN AZIMUTH unusable:

109°-120° byd 25 NM

137°-147°

160°-170°

229°-262° byd 12 NM blo 5,000'

262°-272° byd 15 NM blo 5,000'

ILS/DME 110.7 I-ETI Chan 44 Rwy 09.