

HUMACAO

DR HERMENEGILDO ORTIZ QUINONES (X63) 1 SE UTC-4 N18°08.28' W65°48.04' **PUERTO RICO-VIRGIN ISLANDS**
 35 B NOTAM FILE TJSJ
RWY 10-28: H2458X60 (ASPH) S-20 MIRL 0.4% up W
RWY 10: Tree.
AIRPORT REMARKS: Attended 1130-2000Z. Parachute Jumping. Birds activity on and in/ovf arpt. Skydiving, ultralights opns on arpt. Rising terrain in/ovf arpt. Cattle 500' from thld Rwy 28, occasionally on rwy. Loose stones and gravel on rwy and txy. Ldg fee.
AIRPORT MANAGER: 787-852-8188
COMMUNICATIONS: CTAF 122.8
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665
COMM/NAV/WEATHER REMARKS: Two-way radio communication required for acft and vehicles excp by prior request; Call 787-852-8188.

ISLA DE CULEBRA

BENJAMIN RIVERA NORIEGA (CPX)(TJCP) 1 N UTC-4 N18°18.78' W65°18.23' **PUERTO RICO-VIRGIN ISLANDS**
 49 B LRA NOTAM FILE TJSJ
RWY 13-31: H2600X60 (ASPH) S-12 MIRL 1.4% up NW
RWY 13: Hill.
RWY 31: Fence.
SERVICE: LGT Rtg bcn OTS indef. Rwy 13-31 MIRL-several lts OTS indef.
AIRPORT REMARKS: Unatndd SS-SR. Emergs only. Opns between SS-SR will be an own risk. Birds on and in/ovf rwy. Rapidly rising terrain NW. Low alt maneuvering rqr'd for final alignment to rwy, variable degrees of turbulence may be expd. Acft departing arpt northbound be alert for t/c descending on final for Charlotte Amalie St. Thomas, Cyril E. King (STT). Ldg Rwy 13 only (exc for adverse wx cond). Apch from NW thru Bahia Flamenco hdg 172°. Fly thru Laguna Del Flamenco until aprx parallel to highway in pass alter hdg to 153°, left turn to final. Rapidly rising terrain NW. Rwy, twy pavement cracking, loose stones. Ldg fee for all acft.
AIRPORT MANAGER: 787-742-0022
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665

ISLA DE VIEQUES

ANTONIO RIVERA RODRIGUEZ (VQS)(TJVQ) 3 SW UTC-4 N18°08.09' W65°29.62' **PUERTO RICO-VIRGIN ISLANDS**
 49 B LRA NOTAM FILE TJSJ **L-5C, 6G, A-3G IAP**
RWY 09-27: H4301X75 (ASPH) S-20, D-40 MIRL 0.5% up SW
RWY 09: PAPI(P4L)—GA 3.0° TCH 46'. Thld dplcd 896'. Trees.
RWY 27: Road. Rgt t/c.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 09: TORA-4301 TODA-4301 ASDA-4301 LDA-3405
RWY 27: TORA-4301 TODA-4301 ASDA-4301 LDA-3405
SERVICE: LGT Rtg bcn OTS indef.
AIRPORT REMARKS: Attended 1000-2200Z. VFR opns only. Rising terrain south. Acft not visible from opposite rwy end. Clsd to sked air carrier oper with more than 9 psgr seats and unsked air carrier oper with more than 30 psgr seats. PPR for other B-III acft and max wingspan of 88.75 ft, ctc AMGR. AMGR aftr hrs ph 787-439-5941. Const of twy south of Rwy 09-27. Rwy 09 day landing length 4094, night landing 3405. Rwy 09 dplcd thld marked at 207 ft. No thld lights. Ldg fee for all acft.
AIRPORT MANAGER: 787-729-8715
COMMUNICATIONS: CTAF/UNICOM 123.0
® SAN JUAN CERAP 128.65
CLEARANCE DELIVERY PHONE: For CD ctc San Juan CERAP at 787-253-8664/8665
RADIO AIDS TO NAVIGATION: NOTAM FILE TIST.
ST THOMAS (L) (L) VOR/DME 108.6 STT Chan 23 N18°21.35' W65°01.47' 254° 29.9 NM to fld. 679/10W.
 VOR unusable:
 060°-070° byd 35 NM blo 2,200'
 085°-115° byd 16 NM blo 7,500'
 160°-175° byd 35 NM blo 2,500'
 255°-265° byd 25 NM
 290°-305° byd 15 NM
 DME unusable:
 085°-115° byd 30 NM blo 7,500'
COMM/NAV/WEATHER REMARKS: UNICOM monitored during attendance hrs.

