

CARSON CITY (CXP)(KCXP) 3 NE UTC-8(-7DT) N39°11.54' W119°43.95'

4704 B NOTAM FILE CXP

RWY 09-27: H6101X75 (ASPH-GRVD) S-30, D-60 MIRL

RWY 09: TDZL REIL. PAPI(P2L)—GA 4.0° TCH 56'. Hill. Rgt tfc.

RWY 27: TDZL REIL. PAPI(P2L)—GA 3.0° TCH 41'.

SERVICE: S4 **FUEL** 100LL, JET A **OX** 1, 3 **LGT** ACTIVATE REIL Rwy 09 and 27; TDZL Rwy 09 and 27; MIRL Rwy 09-27—CTAF. PAPI Rwy 09 and 27 on consly. Rwy 09 VGSi unusbl byd 2 NM fm rwy thr; byd 3 degs left and right of cntrln; at ngt. Rwy 27 VGSi unusbl byd 1.3 NM.

AIRPORT REMARKS: Attended 1400-0400Z±. Arpt ops aft hrs ctc fone 775-443-7288. UAS/JAV, ultralight, glider act on and invof arpt.

AIRPORT MANAGER: 775-841-2255

WEATHER DATA SOURCES: AWOS-3PT 119.925 (775) 884-4708.

COMMUNICATIONS: CTAF/UNICOM 123.0

® **NORCAL APP/DEP CON** 119.2

CLNC DEL 133.25

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.

MUSTANG (VH) (H) VORTACW 117.9 FMG Chan 126 N39°31.88'

W119°39.36' 174° 20.6 NM to fld. 5950/16E.

VOR unusable:

002°-012° byd 40 NM blo 19,000'

013°-022° byd 40 NM blo 10,300'

013°-022° byd 53 NM

023°-045° byd 40 NM

079°-113° byd 40 NM

114°-124° byd 40 NM blo 10,000'

114°-124° byd 52 NM

125°-145° byd 40 NM

153°-172° byd 40 NM blo 15,000'

153°-172° byd 52 NM blo 18,000'

173°-186° byd 40 NM

187°-197° byd 40 NM blo 15,000'

187°-197° byd 66 NM

198°-212° byd 40 NM

200°-230° byd 30 NM blo 13,000'

213°-223° byd 40 NM blo 18,000'

224°-304° byd 40 NM

327°-339° byd 40 NM blo 18,000'

356°-001° byd 40 NM

TACAN AZIMUTH unusable:

200°-230° byd 30 NM blo 13,000'

DME unusable:

200°-230° byd 30 NM blo 13,000'

SAN FRANCISCO

L-9A

IAP, AD

