

NDB IRS 382	APP CRS 165°	Rwy Idg 5201
		TDZE 915
		Apt Elev 925

NDB RWY 19




KIRSCH MUNI (IRS)

RADAR required for procedure entry.

Procedure NA at night. Rwy 19 helicopter visibility reduction below 1 SM NA.

MISSED APPROACH: Climb to 2500 then left turn direct IRS NDB and hold.

AWOS-3 121.325	GREAT LAKES APP CON * 121.2 239.25	CLNC DEL 118.325	UNICOM 123.05 (CTAF)
--------------------------	--	----------------------------	--------------------------------



CATEGORY	A	B	C	D
S-19	1520-1	605 (600-1)	1520-1¾	605 (600-1¾)
CIRCLING	1520-1	595 (600-1)	1620-2 695 (700-2)	1620-2¼ 695 (700-2¼)