

# DAVIS MONTHAN THREE DEPARTURE (DMA3.DMA)

TUCSON, ARIZONA

ATIS ★ 132.3 270.1  
 CLNC DEL  
 121.8 275.8  
 GND CON  
 121.8 275.8  
 TOWER  
 118.85 253.5  
 TUCSON APP/DEP CON  
 119.4 269.55

DME required

Rwy	Knots	60	120	180	240	300	360
13 (A)	V/V(fpm)	240	480	720	960	1200	1440
31 (B)	V/V(fpm)	300	600	900	1200	1500	1800


Minimum Climb Rate

(A) to 3200

(B) HOTTT TRANS to 9200

## EFFECTIVE BY NOTAM

During RADAR operations aircraft will receive RADAR vectors to appropriate transition.



(NARRATIVE ON FOLLOWING PAGE) 9413

# DAVIS MONTHAN THREE DEPARTURE (DMA3.DMA)

Orig 28NOV24

TUCSON, ARIZONA  
DAVIS-MONTHAN AFB (KDMA)

SW-4, 28 NOV 2024 to 26 DEC 2024

SW-4, 28 NOV 2024 to 26 DEC 2024