

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS D svc 1530-0500Z† 1 Oct-31 Mar, 1600-0700Z† 1 Apr-30 Sep; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE ADQ.

(H) (H) **VORW/DME** 117.1 ODK Chan 118 N57°46.50' W152°20.39' 239° 5.2 NM to fld. 133/14E.

VOR unusable:

190°-310° byd 15 NM blo 12,000'

DME unusable:

154°-265° byd 15 NM blo 12,000'

266°-305°

306°-341° byd 15 NM blo 12,000'

WOODY ISLAND NDB (HW) 394 RWO N57°46.49' W152°19.48' 241° 5.6 NM to fld. 24/14E.

ILS/DME 110.9 I-ADQ Chan 46 Rwy 26. Class IA. Front unusable within 2.0 DME (0.7 NM from thld). LOC unusable byd 30° r of course.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. RCO available when twr closed.

KODIAK MUNI (KDK)(PAKD) 2 NE UTC-9(-8DT) N57°48.36' W152°22.43'

KODIAK

139 NOTAM FILE ENA

RWY 02-20: H2475X40 (ASPH-TRTD)

RWY 02: Thld dsplcd 240'. Road. Rgt tfc.

RWY 20: Trees.

AIRPORT REMARKS: Attended daylight hrs. CLOSED for ngt ops; unlgtd. Arpt CLOSED High/Low wing except 49ft/under. Unlgtd obstns invof.

Conflicting traffic with Lilly Lake Trident Basin and Kodiak Arpt. Rwy 02-20 nmrs businesses close, smnds rwy. Rwy slps uphill 67 ft fm Rwy 02 dthr to Rwy 20, line of sight btn rwy ends NA. Rwy 02-20 wid varies fm 20 ft Rwy 20 end to 30 ft Rwy 02 end, cracked entire leg. Rwy 02 steel posts and electric panel obstns wi 50 ft of cntrln. First 350 ft of rwy slps 5 pct uphill. Rwy 20 road Xs apch 15 ft blw thr elev 200 ft fm rwy end.

AIRPORT MANAGER: 907-486-8060

COMMUNICATIONS: CTAF 119.8 UNICOM 122.8

RADIO AIDS TO NAVIGATION: NOTAM FILE ADQ.

(H) (H) **VORW/DME** 117.1 ODK Chan 118 N57°46.50'

W152°20.39' 316° 2.2 NM to fld. 133/14E.

VOR unusable:

190°-310° byd 15 NM blo 12,000'

DME unusable:

154°-265° byd 15 NM blo 12,000'

266°-305°

306°-341° byd 15 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. Tfc advzy Kodiak twr—119.8.



KODIAK/LILLY LAKE SPB (9Z3) 1 NE UTC-9(-8DT) N57°48.16' W152°22.96'

KODIAK

130 LRA NOTAM FILE ENA

WATERWAY NE-SW: 2100X250 (WATER)

WATERWAY NE: Rgt tfc.

SEAPLANE REMARKS: Unattended. Arpt clsd at ngt. Arpt CLOSED High/Low wing except 49 ft and under. Windssock lctd at Kodiak Muni. Numerous unlit obstns invof. ALERT: psbl conflicting tfc with NE ops and lake ops. Steel posts and electric panel obstns wi 100 ft N end of lake near cntrln. Lake docks, ramps and property pvt—Amgr.

AIRPORT MANAGER: 907-486-8060

COMMUNICATIONS: CTAF 119.8 UNICOM 122.8

RADIO AIDS TO NAVIGATION: NOTAM FILE ADQ.

(H) (H) **VORW/DME** 117.1 ODK Chan 118 N57°46.50'

W152°20.39' 306° 2.2 NM to fld. 133/14E.

VOR unusable:

190°-310° byd 15 NM blo 12,000'

DME unusable:

154°-265° byd 15 NM blo 12,000'

266°-305°

306°-341° byd 15 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For toll free call to Kenai FSS dial 1-866-864-1737. Tfc adzy: Kodiak ATCT—119.8.

