ALASKA

| SEYMOUR LAKE SPB (3A3) 320 NOTAM FILE ENA | | UTC-9(-8DT) | N61º36.81 | W149°39.93′ | ANCHORAG |
|--|--------------|--------------------|---------------------|--------------------------------|---------------------|
| WATERWAY N-S: 6000X400 (W | ATER) | | | | |
| SERVICE: S4 | subject to | the Matanuska | Susitaa Borough | motorized uses on water bodie | s which regulates |
| "annoying noises" between | | | | motorized uses on water bould | s which regulates |
| , , | | | | ecommended for seaplane use | due to sharp rocks |
| and trees in immediate vic | inity. | | | | |
| AIRPORT MANAGER: 907-841-4 | 069 | | | | |
| COMMUNICATIONS: CTAF 122.8 Comm/Nav/Weather Remarks: F | or a tall fi | oo ooll to Konoi I | ESS dial 1 SEE | 964 1727 | |
| | | | | | |
| SOLOY STRIP (87AK) PVT | | UTC-9(-8DT) | N61°39.09′V | V149º17.31′ | ANCHORAG |
| 545 NOTAM FILE Not in RWY 07-25: 1100X50 (GRVL) | sp. | | | | |
| RWY 07: Trees. | | | | | |
| RWY 25: Trees. Rgt tfc. | | | | | |
| AIRPORT REMARKS: Attended M | on–Fri 17 | 00–0200Z‡. | | | |
| AIRPORT MANAGER: (907) 315- | 5300 | | | | |
| COMMUNICATIONS: CTAF 122.8 Comm/Nav/Weather Remarks: F | or a tall fi | aa aall ta Kanai l | ESS dial 1 SEE | 964 1727 | |
| | | | | | |
| | (3K9) | 2 E UTC-9(-8 | DT) N61º35. | 33′W149º23.10′ | ANCHORAG |
| 330 NOTAM FILE ENA | | | | | |
| WATERWAY NE-SW: 5500X800 SEAPLANE REMARKS: Unattender | · , | av not monitore | d recommend | 061° 16.7 NM From Big Lake | |
| visual inspection prior to u | | · | , | "BGQ" VORTAC | |
| Haul out facility avbl PPR | | | | | |
| avbl call 907–376–2288. | | | | | |
| property on lake perimeter | | | | | DWNY: |
| south side of lake. Be alert: | | | - | | TERRI |
| drifts and strong NE winds and outlet. Be alert for boa | | | | NE-SW W | |
| and floating debris. | ters, wat | | lucinine uctivity | 5500 | |
| AIRPORT MANAGER: 907-376-2 | 118 | | | | .* |
| COMMUNICATIONS: CTAF 122.8 | | | | | |
| RADIO AIDS TO NAVIGATION: NOT | | | NC1024 17/ | | |
| BIG LAKE (H) (H) VORTACW 11. W149°58.03′ 067° | | to fld. 179/19E. | | | V |
| TACAN AZIMUTH unusabl | | 10 1101 17 5, 152 | | | <u>}</u> |
| 230°-245° byd 38 blo | 8,000´ | | | | T I |
| DME unusable: 230°–245° byd 38 blo | 8 000′ | | | k the | |
| COMM/NAV/WEATHER REMARKS: F | | ee call to Kenai I | FSS dial | | < |
| 1-866-864-1737. | | | | | |
| VALLEY FLYING CROWN (AK) | 27) D\/T | | | °38.55′ W149°37.47′ | ANCHORAG |
| 400 NOTAM FILE Not in | , | 51444 010- | -9(-001) 1101 | 56.55 W145 57.47 | Alteriolia |
| RWY 06-24: 1800X30 (GRVL) | -1 | | | | |
| RWY 24: Rgt tfc. | | | | | |
| | . Power li | ne along south si | ide of rwy. Strip i | not maintained in winter. Rwy | soft during spring |
| break-up. | 020 | | | | |
| AIRPORT MANAGER: 907-232-3 Communications: CTAF 122.8 | 930 | | | | |
| COMM/NAV/WEATHER REMARKS: F | or a toll fr | ee call to Kenai I | FSS dial 1–866– | 864–1737. | |
| | | | | | |
| VISNAW LAKE SPB (T66) 300 NOTAM FILE ENA | 7 NW L | JTC-9(-8DT) | N61º37.14' W | 149°40.71′ | ANCHORAG |
| WATERWAY N-S: 4000X200 (W | ATER) | | | | |
| WATERWAY S: Rgt tfc. | /(121() | | | | |
| SEAPLANE REMARKS: Unattende | d. Tsnt sv | c not authorized. | Ctn: Hvy tfc are | a; nmrs SPBs & arpts invof. Re | creation boats invo |
| - | | wo TGL not auto | rizied. Mntn tfc p | oat W of lake. Grvl ramp E sho | e. |
| AIRPORT MANAGER: 907-947-4 | 052 | | | | |
| COMMUNICATIONS: CTAF 122.8 | | | | | |
| COMM/NAV/WEATHER REMARKS: F | م الحلم م | an nall to Key 12 | | 064 1727 | |