SALEM AIRPARK         (38D)         3 N         UTC-5(-4DT)         N40°56.88' W80°51.72'         DETRI           1162         NOTAM FILE CLE         L-3         RWY 10L-28R: H3404X50 (ASPH)         S-8         LIRL(NSTD)         0.3% up E         I         RWY 10L-28R: H3404X50 (ASPH)         S-8         LIRL(NSTD)         0.3% up E         I         RWY 10L: Trees.         I         RWY 10L: Trees.         I         RWY 10R-28L: 2550X60 (TURF)         0.4% up E         RWY 10R-76E.         RWY 10R-76E.         I         RWY 10R-76E.         I <td< th=""><th></th></td<>	
RWY 10R: Trees. RWY 281- Pole	
<ul> <li>SERVICE: FUEL 100LL LGT Actvt nstd LIRL Rwy 10L–28R—CTAF. Rwy 10L–28R nstd LIRL due to layout and colors; Rw 10L lgtd 238' from rwy end; Rwy 28R lgtd 330' from rwy end with 360° green lgts.</li> <li>AIRPORT REMARKS: Attended ireg. Deer, birds, and wildlife on and invof arpt. Dragstrip 3500 ft southeast looks like arpt. Al pavement restricted acft max gwt less than 8000 lbs. Rwy 10R–28L cct amgr for turf conds prior to use. Rwy 10L–28 marking non–standard due to yellow DTHR. Rwy 10L–28R nonly 2829 ft avbl for ngt ops. Rwy 10L–28R wdspr cracking Rwy 10L: marking faded. Rwy 28R: marking faded. Rwy 28R: acft on turn fm downwind to base may be obsc by tree in apch. Fuel: 100LL avbl H24 self svc via credit card.</li> </ul>	II BR g.
AIRPORT MANAGER: 724-316-6026	
COMMUNICATIONS: CTAF/UNICOM 122.7 ® Cleveland App/dep con 125.5 (1100–0600Z‡).	
CLEVELAND AFFIGE FOR 122.5 (1100-000024). (B) CLEVELAND CENTER APP/DEP CON 120.6 (0600-1100Z‡) ctc Cleveland ARTCC at 440-774-0223. CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.	
RADIO AIDS TO NAVIGATION: NOTAM FILE YNG.	
YOUNGSTOWN (L) TACAN Chan 27 YNG (109.0) N41°19.86′W80°40.48′ 205° 24.5 NM to fld. 1158/5W.	

OHIO

313

SANDUSKY CO RGNL (See FREMONT on page 287)

SEAGATE HELISTOP HELIPORT (See TOLEDO on page 317)

## SEBRING

TRI-CITY (3G6) 1 SE UTC-5(-4DT) N40°54.36′ W81°00.00′	DETROIT
1188 NOTAM FILE CLE	L-29B
RWY18–36: H2768X45 (ASPH) LIRL(NSTD)	IAP
RWY 36: Pole.	
SERVICE: FUEL 100LL LGT Actvt NSTD LIRL Rwy 18-36-CTAF. Rwy 18-36 NSTD LIRL due to layout, c	olors and
non-frangible fixtures.	
AIRPORT REMARKS: Unattended. Deer, birds, & wildlife on & invof arpt. Fuel avbl upon request, call amgr. Rwy 18-	36 excessive
cracking, vegetation thru cracks & joints, & uneven rough pavement. Rwy 18 nstd basic due to nrs layout &	size. Cntrln
faded. Rwy 36 nstd basic due to nrs layout & size. Cntrln faded.	
AIRPORT MANAGER: 330-428-1269	
COMMUNICATIONS: CTAF 122.9	
® CLEVELAND APP/DEP CON 125.5 (1100–0600Z‡)	
$\mathbb{R}$ CLEVELAND CENTER APP/DEP CON 120.6 (0600–1100Z <sup>‡</sup> ) ctc Cleveland ARTCC at 440–774–0223.	
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCO	Cat
440-774-0223/0490.	Jut
RADIO AIDS TO NAVIGATION: NOTAM FILE CAK.	
	07/414
AKRON (L) (L) VORW/DME 114.4 ACO Chan 91 N41°06.47′ W81°12.09′ 147° 15.2 NM to fld. 119	97/400.
DME unusable:	
Byd 10 NM	

SENECA CO (See TIFFIN on page 316)