## ILLINOIS

<ul> <li>HARVARD</li> <li>DACY (ØCØ) 1 SW UTC-6(-5DT) N42°24.15' W88°37.94'</li> <li>913 TPA—1513(600) NOTAM FILE IKK</li> <li>RWY 09-27: 3589X105 (TURF) 0.4% up E</li> <li>RWY 09-27: 3589X105 (TURF) 0.4% up E</li> <li>RWY 14-32: 2633X100 (TURF)</li> <li>RWY 14-32: 2633X100 (TURF)</li> <li>RWY 14-32: 2633X100 (TURF)</li> <li>RWY 14-36: 2577X120 (TURF) LIRL(NSTD)</li> <li>RWY 18-36: 2577X120 (TURF) LIRL(NSTD)</li> <li>RWY 18: Thild dspied 305'. Road.</li> <li>SERVICE: S4 FUEL 100LL LGT Rwy 18–36 NSTD LIRL; NSTD spacing and non-frangible. Rwy 18–36</li> <li>AIRPORT REMARKS: Attended 1400–230024. Rwy 09 and Rwy 14 dspied thid marked with white tires. Rw</li> <li>marked with white tires and orange and white barrels. Seasonal crops at Rwy 09, Rwy 27, Rwy 36, R</li> <li>AIRPORT MANAGER: 815-943-9876</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>CLEARANCE DELIVERY PHONE: FOr CD ctc Chicago ARTCC at 630-906-8921.</li> </ul>	y 18 dsplcd thid
HAVANA RGNL (91Ø) 5 SE UTC-6(-5DT) N40°13.36' W90°01.37' 488 B NOTAM FILE IKK RWY 09-27: 2235X100 (TURF) MIRL SERVICE: FUEL 100LL AIRPORT REMARKS: Attended irregularly. Self svc fuel avbl 24 hrs. AIRPORT MANAGER: 309-543-9006 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc St Louis Apch 314-890-1017.	CHICAGO
HIGHLANDWINET       (HØ7)       3 NE       UTC-6(-5DT)       N38°46.76' W89°38.43'         537       NOTAM FILE STL         RWY 18-36: 2200X100 (TURF)         RWY 18: Thild dsplcd 180'.         RWY 36: Thild dsplcd 354'. Road. Rgt tfc.         AIRPORT REMARKS: Unattended. Extensive glider ops along W side of rwy; gliders fly opposite pattern to pow         18-36 dsplcd thids marked with white in-ground markings, also both sides of rwy marked with white in         To assure firm turf; do not taxi S of above ground fuel tank. Administration bldg can be accessed by pu         and 4 together, then 3.         AIRPORT MEMAER: 618-977-3857         COMMUNICATIONS: CTAF 122.9         CLEARANCE DELIVERY PHONE: For CD ctc St Louis Apch at 314-890-1017.	in–ground stripes.
<ul> <li>HINCKLEY (ØC2) 3 W UTC-6(-5DT) N41°46.25' W88°42.20'</li> <li>760 NOTAM FILE IKK</li> <li>RWY 09-27: 2640X100 (TURF)</li> <li>AIRPORT REMARKS: Attended irregularly. Glider ops surface-17,500'. Rwy 09-27 not plowed; use at own nunsable under very wet conditions.</li> <li>AIRPORT MANAGER: 316-213-7093</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>CLEARANCE DELIVERY PHONE: For CD ctc Chicago Apch at 847-289-0926.</li> </ul>	CHICAGO risk. Arpt may be
HUSKK N39°46.39′ W89°45.59′ NOTAM FILE SPI. NDB (MHW/LOM) 382 SP 043° 5.7 NM to Abraham Lincoln Capital. 602/1W.	ST. LOUIS L–27C
ILLINOIS VALLEY RGNL-WALTER A DUNCAN FLD (See PERU on page 79)	
INGERSOLL (See CANTON on page 36)	