

MINNEAPOLIS CITY CO (45K) 2 SW UTC-6(-5DT) N39°05.66' W97°43.26'

WICHITA
L-101

1246 NOTAM FILE ICT

RWY 16-34: H3970X20 (ASPH)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Attended Apr-Nov dawn-dusk. Arprt opr daylight hrs only.

Deer on and infov arprt.

AIRPORT MANAGER: 785-392-3300

COMMUNICATIONS: CTAF 122.9

Ⓡ **KANSAS CITY CENTER APP/DEP CON** 134.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.

SALINA (VH) (H) VORTACW 117.1 SLN Chan 118 N38°55.51'

W97°37.28' 328° 11.2 NM to fld. 1316/7E.


VOR unusable:

017°-026° byd 40 NM

315°-016° byd 15 NM blo 6,000'

DME unusable:

300°-042° byd 15 NM blo 6,000'



MOLINE

ELK CO (2K6) 3 NE UTC-6(-5DT) N37°22.86' W96°16.27'

KANSAS CITY

1063 NOTAM FILE ICT

RWY 18-36: H2510X40 (ASPH) 0.4% up N

RWY 36: Pole.

AIRPORT REMARKS: Unattended. Wildlife on and infov arprt. Rwy 18-36 has centerline marking only. Rwy 36 the poles that constitute the controlling obstruction on the right are not visibly marked or lgted.

AIRPORT MANAGER: 620-374-3597

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

MONTEZUMA MUNI (K17) 2 SW UTC-6(-5DT) N37°35.14' W100°28.21'

WICHITA
L-15C

2780 NOTAM FILE ICT

RWY 17-35: H4000X60 (ASPH) MIRL

RWY 17: Thld displcd 700'. Road.

RWY 35: Road.

SERVICE: LGT ACTIVATE MIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. +6 ft irrigation engine/pump located on Rwy 17-35 W edge near windsock.

AIRPORT MANAGER: 620-846-0550

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

MORITZ MEML (See BELOIT on page 88)