

**MORRISTOWN MUNI** (MMU)(KMMU) P (A) 3 E UTC-5(-4DT) N40°47.96' W74°24.89'

**NEW YORK**

187 B TPA—See Remarks NOTAM FILE MMU

**COPTER**

**RWY 05-23:** H5998X150 (ASPH-GRVD) S-30, D-80, 2S-101

**H-101, 121, L-33A, 34H**

PCN 25 F/C/X/T HIRL

**IAP, AD**

**RWY 05:** REIL. Trees.

**RWY 23:** MALS.R.

**RWY 13-31:** H3997X150 (ASPH-GRVD) S-30 PCN 11 F/C/X/T MIRL

**RWY 13:** Trees.

**RWY 31:** REIL. PAPI(P2L)—GA 3.5° TCH 39'. Trees.

**SERVICE:** FUEL 100LL, JET A, A+ OX 1, 2, 3, 4 LGT Dusk-Dawn;  
ACTVT HIRL Rwy 05-23, MIRL Rwy 13-31, REIL Rwy 05 and 31,  
MALS.R Rwy 23, and PAPI Rwy 31—CTAF. **MILITARY—FUEL**  
(NC-100LL, A+)

**NOISE:** Noise abatement procedures in effect, ctc Noise Abatement Office  
973-538-3366 extension 122. All arrival/departure acct follow  
manufacturers recommended procedures for quiet ops and minimum  
noise. Voluntary noise abatement proc include avoiding TGL ops on  
Rwy 13-31.

**AIRPORT REMARKS:** Attended 1145-0330Z†. Birds and deer on and invof  
arpt. When twr clsd all acct and vehicles must state intentions on CTAF  
before ops on any rwy. ARFF svc avbl 24 hrs daily. For ARFF svcs when  
twr clsd ctc ARFF station—CTAF or 973-455-1953. Inbound ttc  
request FBO svcs, instructions, and ramp advisories 30 min prior to  
arrival. After ldg ctc FBO again 129.6 for preferred ramp entrance to Twy D or Twy J. No TGL on Rwy 13-31 unless the  
crosswind vclty for Rwy 05-23 exceeds 10 kts. No turbojet ldg on Rwy 13 and Rwy 31 unless the cross wind velocity for  
Rwy 05-23 exceeds 16 kts. TPA—1200(1013) lgt acct, 1700(1513) heavy acct. Acct carrying explosive cargo PPR before  
ldg, call 973-538-6400. Helicopter ops over residential areas blo 1000' MSL should be avoided. Route 80 visual apch  
preferred for Rwy 23. During snow removal ops 15 minute prior notice required on 118.1 and no practice low apchs or  
touch and go ldgs. Taxilane K N of FBO ramp, no hel or acct with a wingspan gtr than 50 ft. US Customs avbl Mon-Fri  
1300-2100Z†, between 2101-1259Z† and weekends call 973-267-0302 for appointment. Morristown customs  
association fees apply, ctc arpt manager 973-538-6400 for details. Stage I departure fee 0400-1145Z†. Ldg fee. User  
fee arpt. Flight Notification Service (ADCUS) avbl. NOTE: See Special Notices—Arrival Alert.

**AIRPORT MANAGER:** 973-538-6400

**WEATHER DATA SOURCES:** AWOS-3 (973) 290-0135 LAWRS.

**COMMUNICATIONS:** CTAF 118.1 ATIS 124.25

Ⓡ **NEWARK APP CON** 127.6

**TOWER** 118.1 (1145-0330Z†) **GND CON** 134.2 **CLNC DEL** 128.6

Ⓡ **NEWARK DEP CON** 119.2

**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc newark Apch at 800-645-3206.

**AIRSPACE:** CLASS D svc 1145-0330Z†; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE TEB.

**TETERBORO (T) (T) VORW/DME** 108.4 TEB Chan 21 N40°50.92' W74°03.73' 271° 16.3 NM to fld. 8/11W.

DME unusable:

060°-080° byd 22 NM blo 2,500'

081°-120° blo 4,000'

121°-180° blo 3,000'

236°-246°

VOR unusable:

081°-120° blo 4,000'

121°-180° blo 3,000'

236°-246°

**ILS** 110.3 I-MMU Rwy 23. Class IB. Unmonitored when ATCT closed. Glideslope unusable for cpd apchs blw  
875'.

