

SCHUYLerville

GARNSEYS (BØ4) 1 S UTC-5(-4DT) N43°04.06' W73°35.03'

NEW YORK

100 NOTAM FILE BTV
RWY 02-20: 2500X90 (TURF)
RWY 02: Road.
RWY 20: Road.

AIRPORT REMARKS: Attended May-Sep dalgt hours. Arprt open dalgt hours only. Numerous buildings in apch to Rwy 20. Tiedowns located immediately north of driveway adjacent to Rwy 20 end.

AIRPORT MANAGER: 518-469-9472

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

WATERWAY 02W-20W: 9999X750 (WATER)

SENECA FALLS

FINGER LAKES RGNL (ØG7) 2 SE UTC-5(-4DT) N42°53.01' W76°46.87'

NEW YORK

492 B NOTAM FILE BUF

L-32F

RWY 01-19: H4592X75 (ASPH) S-12.5, D-30 MIRL
RWY 01: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dsplcd 392'. Trees.
RWY 19: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Crops.

RWY 11-29: 1850X60 (TURF) 1.3% up W
RWY 11: Trees.
RWY 29: Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 01: TORA-4592 TODA-4592 ASDA-4592 LDA-4199
RWY 19: TORA-4592 TODA-4592 ASDA-4592 LDA-4292

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 01 and Rwy 19; MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended 1300-2100Z†. Medivac heliport flight svc on arprt, monitor CTAF for ops. 25' unmkd tension wire xng 20' east of Rwy 29 thld. Ldg fee. Ldg fee for jets and turbo props.

AIRPORT MANAGER: 315-539-1640

WEATHER DATA SOURCES: AWOS-3 120.0 (315) 568-5362.

COMMUNICATIONS: CTAF/UNICOM 122.8


- Ⓡ **ELMIRA APP CON** 124.3 (SW-SE) (1100-0500Z†)
- Ⓡ **NEW YORK CENTER APP CON** 133.35 (SW-SE) (0500-1100Z†)
- Ⓡ **ROCHESTER APP CON** 119.55 (W-NW)
- Ⓡ **SYRACUSE APP/DEP CON** 126.125

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.

RADIO AIDS TO NAVIGATION: NOTAM FILE ITH.

ITHACA (L) DME 111.8 ITH Chan 55 N42°29.70' W76°27.58' 329° 27.3 NM to fld. 1112.

DME unusable:
 360°-160° byd 20 NM blo 6,500'



SHARON (K31) 2 SE UTC-5(-4DT) N42°46.70' W74°34.66'

NEW YORK

1508 NOTAM FILE BUF

RWY 13-31: 2570X120 (TURF)

RWY 13: Thld dsplcd 200'. Trees.
RWY 31: Trees.

AIRPORT REMARKS: Attended irregularly. P-line parallel on SW side of rwy 285 ft from rwy edge. Rwy shortened by 200' on the west end due to turf holes/crevasses. Trees encroaching NE side of rwy.

AIRPORT MANAGER: 518-284-2081

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.