

**BAMBERG CO** (99N) 5 W UTC-5(-4DT) N33°18.27' W81°06.51'

231 B NOTAM FILE AND

**RWY 05-23:** H3603X60 (ASPH) S-30, D-60 MIRL 0.6% up NE

**RWY 05:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.

**RWY 23:** PAPI(P2L)—GA 3.0° TCH 41'. Tree.

**SERVICE:** FUEL 100LL LGT Actvt PAPI Rwy 05 & 23; MIRL Rwy 05-23—CTAF.

**AIRPORT REMARKS:** Unattended.

**AIRPORT MANAGER:** 803-245-5191

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓜ **COLUMBIA APP/DEP CON** 124.15

**CLEARANCE DELIVERY PHONE:** For CD ctc Columbia Apch at 803-822-5242 or 803-822-5040.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE AND.

**ALLENDALE (VL) VOR** 116.7 ALD N33°00.75'

W81°17.53' 029° 19.8 NM to fld. 187/1W.

VOR unusable:

019°-029° byd 40 NM blo 3,000'

019°-029° byd 52 NM

030°-084° byd 16 NM blo 6,000'

030°-084° byd 26 NM

085°-109° byd 40 NM

110°-120° byd 40 NM blo 6,000'

110°-120° byd 48 NM

110°-200° blo 3,000'

110°-200° byd 16 NM blo 6,000'

121°-187° byd 40 NM

198°-200° byd 40 NM

260°-269° byd 40 NM

270°-286° byd 40 NM blo 3,000'

270°-286° byd 59 NM

300°-302° byd 40 NM

315°-319° byd 40 NM

320°-330° byd 40 NM blo 4,000'

320°-330° byd 46 NM

325°-002° byd 31 NM blo 2,400'

331°-335° byd 40 NM

340°-005° byd 40 NM

CHARLOTTE

L-241

IAP

