

**OROVILLE MUNI** (OVE)(KOVE) 3 SW UTC-8(-7DT) N39°29.27' W121°37.32'

SAN FRANCISCO

194 B TPA-994(800) NOTAM FILE OVE

H-3B, L-2G

RWY 02-20: H6020X100 (ASPH) S-47, D-90 HIRL

IAP

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 44'.

RWY 20: REIL. PAPI(P2L)—GA 3.0° TCH 40'.

RWY 13-31: H3540X100 (ASPH) S-19, D-31 HIRL 0.4% up NW

RWY 13: PAPI(P2L)—GA 3.0° TCH 39'.

RWY 31: PAPI(P2L)—GA 3.0° TCH 29'. Trees.

**SERVICE:** S3 FUEL 100LL, JET A LGT ACTVT REIL Rwy 02 and 20;  
PAPI Rwy 02, 13, 20 and 31; HIRL Rwy 02-20 and Rwy  
13-31—CTAF. VGSi Rwy 20 does not provide obstruction clearance  
byd 3 NM.

**AIRPORT REMARKS:** Attended Mon-Sat 1600-0100Z±. For Arpt  
information Mon-Fri ctc (530) 538-2490. Firefighting acct invof arpt  
May-Oct. Twy from Rwy 02-20 to golf course/restaurant tiedowns  
20' wide with no shoulders.

**AIRPORT MANAGER:** 530-538-2490

**WEATHER DATA SOURCES:** ASOS 121.425 (530) 533-5792.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ **NORCAL APP/DEP CON** 125.4

**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-6874.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MYV.

**MARYSVILLE (VL) (DL) VOR/DME** 110.8 MYV Chan 45 N39°05.92' W121°34.38' 338° 23.4 NM to fld. 62/116E.

VOR unusable:

013°-089° byd 25 NM

015°-089° byd 25 NM

184°-194° byd 25 NM

199°-225° byd 25 NM

207°-217° byd 25 NM

260°-301° byd 58 NM

275°-295° byd 28 NM blo 6,000'

297°-300° byd 25 NM

DME unusable:

275°-295° byd 28 NM blo 6,000'

