

STERLING MUNI (STK)(KSTK) 3 W UTC-7(-6DT) N40°36.86' W103°15.86'

CHEYENNE

4038 B NOTAM FILE DEN

H-5A, L-10G

RWY 15-33: H5201X75 (ASPH) S-30 MIRL

RWY 15: REIL. PAPI(P2L)—GA 3.0° TCH 44'. Tree.

RWY 33: REIL. PAPI(P2L)—GA 3.0° TCH 44'.

IAP

RWY 04-22: 2809X150 (TURF-GRVL)

RWY 04: Road.

RWY 22: Tree.

SERVICE: FUEL 100LL, JET A LGT When ATCT CLSD ACTVT REIL RWY 15 and RWY 33; MIRL RWY 15-33—CTAF. PAPI RWY 15 and RWY 33 OPR consly. INCR MIRL INTST—CTAF.

AIRPORT REMARKS: Attended 1400-2300Z±. For after hrs svc call 970-520-2325. Aerobatic OPS on and INVOF ARPT. Be alert; intensive USAF student TRG INVOF KCOS and KPUB airports. RWY 04-22 soft and rough when wet. Varmint holes near Rwy 04 end. Intensive AG OPS MAR-SEPT. RWY 04-22 ends MKD with red/green reflectors. TWY and TRML tiedown area MKD with blue reflectors. RWY 04 DEP has 8 FT fence 155' FT FM DEP end of RWY. NOTE: See Special Notices—Aerobatic Operations in Colorado.

AIRPORT MANAGER: 970-522-0417

WEATHER DATA SOURCES: AWOS-3 118.525 (970) 526-3009.

COMMUNICATIONS: CTAF/UNICOM 122.8


CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE AKO.

AKRON (VH) (H) VORW/DME 114.4 AKO Chan 91 N40°09.33' W103°10.78' 339° 27.8 NM to fld. 4623/13E.

VOR unusable;

228°-232° byd 40 NM



STEVENS FLD (See PAGOSA SPRINGS on page 363)

SUNLIGHT MOUNTAIN 5SM N39°25.53' W107°22.75'/10603
AWOS-3 126.075 (970) 384-3380 AWOS visibility unreliable indef.

DENVER

L-9E