

YERINGTON MUNI (043) 1 N UTC-8(-7DT) N39°00.32' W119°09.39'

4382 B TPA—5182(800) NOTAM FILE RNO

RWY 02-20: H5822X75 (ASPH) S-24, D-32 MIRL

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Antenna.

RWY 20: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Trees.

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 02 and 20; MIRL Rwy 02-20—CTAF. PAPI Rwy 02 and 20 on consly. Rwy 02 PAPI unusbl byd 3.0 NM fm rwy thr due to trrn.

AIRPORT REMARKS: Attended Mon-Fri 1500-0200Z†, Sat-Sun irregularly.

AIRPORT MANAGER: 775-431-4534

COMMUNICATIONS: CTAF/AUNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.

HAZEN (L) VORTAC 114.1 HZN Chan 88 N39°30.98' W118°59.86' 177° 31.5 NM to fld. 4086/17E.

VOR portion unusable:
300°-320° byd 30 NM blo 9,500'

SAN FRANCISCO

H-3C, L-9A

IAP

