

TAMPA, FLORIDA

ILS or LOC RWY 5

LOC I-MCF
109.5

APCH CRS
044°

Rwy Idg **11,421**
TDZE **10**
Arpt Elev **14**

AL-418 [USAF]

MACDILL AFB (KMCF)

RADAR or DME required.

*When ALS inop, increase RVR to 40, vis to ¾ mile.

**When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE RVR to 60, vis to 1½ miles.

ALSF-1

MISSED APPROACH: Climb to 2700 via MCF TACAN R-075 to MCF 22 DME and hold. Cross 8 DME at 1700. RNAV or ATC RADAR required for missed approach.

ATIS
133.825 270.1

TAMPA APP CON
124.95 354.0

TOWER
120.175 294.7

GND CON
118.575 275.8

***Circling not authorized NW of Rwy 5-23.

CAUTION:
LOC course offset 2.86° from the extended rwy centerline and intersects the rwy centerline 1834' after the DA.

WARNING: Use extreme caution PETER O. KNIGHT airport 4 NM Northeast of MACDILL AFB.

Expect RADAR vectors around St. Petersburg landmark for noise abatement, unless otherwise requested by pilot.

ELEV	14	TDZE	10
------	----	------	----

CATEGORY	A	B	C	D	E
S-ILS 5 *	260/24		250	(300-½)	
S-LOC 5 **	420/24	410 (500-½)	420/40	410	(500-¾)
*** CIRCLING	500-1 486 (500-1)	540-1 526 (600-1)	540-1½ 526 (600-1½)	580-2 566 (600-2)	1020-3 1006(1100-3)

TAMPA, FLORIDA

27°51'N-82°31'W

MACDILL AFB (KMCF)

HIRL Rwy 5-23

FAF to MAP 4.3 NM

Knots	60	90	120	150	180
Min:Sec	4:18	2:52	2:09	1:43	1:26

SE-3, 23 JAN 2025 to 20 FEB 2025

SE-3, 23 JAN 2025 to 20 FEB 2025

ILS or LOC RWY 5

TAMPA, FLORIDA

Amtd 1 18MAY23

27°51'N-82°31'W

MACDILL AFB (KMCF)