

RNAV (GPS) RWY 18R
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

MISSED APPROACH: Climb to 3100 direct BOSAC and hold.

30 NM to HAGUR (NoPT) 3700

17 NM to HAGUR 3000

HAGUR

095° 275°

HAGUR 3000

12 NM to HAGUR

30 NM to HAGUR 3700

CAUTION: Numerous migratory bird flocks in area. Wildlife Refuge Area south of airport.

WHEELER NATIONAL WILDLIFE REFUGE

7 NM HOLD 5000 3000

185°

005°

(IF/IAF) HAGUR

2500

185° (6.6)

1946

(FAF) FEKER

1282

ZISTI 2.9 NM to RW18R

809°

RW18R

796±

812

1066

R-2104C

R-2104B

R-2104A

1436

1935

2673

2010

2379

MISSED APCH FIX BOSAC

185°

005°

7 NM

ELEV 629 D TDZE 629

185° to RW18R

818

181

688

TWR 854±

12600 X 150

10001 X 150

36R

36L

3100 BOSAC

7 NM Holding Pattern

HAGUR

005° 5000

185° 3000

2500

1600

1.2 NM to RW18R

2.9 NM to RW18R

FEKER 2500

ZISTI 2.9 NM to RW18R

1.2 NM

1.7 NM

2.8 NM

6.6 NM

GP 3.00° TCH 56

CATEGORY	A	B	C	D	E
LPV DA	829/18 200 (200-½)				
INAV/VNAV DA	954/26 325 (400-½)				
INAV MDA	1060/24	431 (500-½)	1060/40	431 (500-¾)	
C CIRCLING	1160-1	531 (600-1)	1160-1½ 531 (600-1½)	1240-2 611 (700-2)	1260-2¼ 631 (700-2¼)

TDZ/CL Rwy 18R and 36L
HIRL Rwy 18L-36R and 18R-36L

HUNTSVILLE INTL-CARL T JONES FLD (HSV)
34°38'N-86°47'W **RNAV (GPS) RWY 18R**