KANSAS CITY (H) (H) VORTACW 113.25 MCI Chan 79(Y) N39°17.12 W94°44.22 175° 26.2 NM to fid. 1017/5E. HERBB NDB (LOMW) 420 PK N38°45.19' W94°44.21' 356° 5.7 NM to fld. 1103/4E. NOTAM FILE OJC.

cone—CTAF. VASI Rwy 18 and Rwy 36 opr continuously. AIRPORT REMARKS: Attended continuously. To confirm snow removal and winter conditions Nov-Apr call 913-715-6005. Birds, waterfowl, wildlife on and invof arpt. It is advised that rotocraft avoid the overflights of surrounding neighborhoods. Upon takeoff for Rwys 18 and 36 maintain rwy heading until passing 1,600' MSL. TPA-low performance acft 2096 (1000), high performance acft 2596 (1500). AIRPORT MANAGER: 913-715-6002

WEATHER DATA SOURCES: ASOS (913) 780-6969 LAWRS. COMMUNICATIONS: CTAF 126.0 ATIS 119.35 913-764-9272

EXECUTIVE TOWER 126.0 (1300-0300Z‡) GND CON 121.6

COMM/NAV/WEATHER REMARKS: Freq 121.5 not available at tower.

AIRSPACE: CLASS D svc 1300-0300Z[‡]; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE MCI.

HELIPORT REMARKS: Helipad H1 CLOSED indefinitely.

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc MCI Apch at 816-329-2710.

LOC/DME 111.1 I-OJC Chan 48 Rwv 18. Unmonitored when twr clsd. LOC 108.3 I-PKX Rwy 36. LOM HERBB NDB. Unmonitored when tower clsd.

NEW CENTURY AIRCENTER (IXD)(KIXD) P (AR) 4 SW UTC-6(-5DT) N38º49.86' W94º53.42' B TPA—See Remarks NOTAM FILE IXD 1087 RWY 18-36: H7339X150 (ASPH) S-75, D-175, 2S-175, 2D-350

PCN 28 F/C/X/U HIRL 0.5% up N RWY 18: REIL. VASI(V2L)-GA 3.0° TCH 46'. RWY 36: MALSR. Rgt tfc. RWY04-22: H5132X100 (ASPH) S-47, D-55 PCN 16 F/C/Y/U MIRL 0.5% up NF

RWY 04: PAPI(P4L)-GA 3.0° TCH 41'. Rgt tfc. RWY 22: PAPI(P4L)-GA 3.0° TCH 45'.

SERVICE: S4 FUEL 100LL, JET A 0X 1, 2, 3, 4 LGT When twr clsd ACTIVATE HIRL Rwy 18-36, MIRL Rwy 04-22, MALSR Rwy 36, REIL Rwy 18, twy lgts, and wind cone -CTAF. VASI Rwy 18, PAPI Rwy 04-22 opr continuously. MILITARY -FUEL A+ (C913-782-9003/fax-1555.) (NC-100LL, A)

AIRPORT REMARKS: Attended Sun-Thu-all hrs, Fri-Sat 1200-0500Z‡. To confirm snow removal and winter conditions Nov-Apr call 913-715-6005. Birds and waterfowl on and invof arpt. TPA-single engine acft 2087 (1000), multi engine/turbine acft 2587 (1500). Twr view of southwest end of Twy F and Rwy 04-22 is obscured. Low sun angles reduce visibility when crossing Rwy 18-36 from Twy A or B. AIRPORT MANAGER: 913-715-6002

WEATHER DATA SOURCES: ASOS 135.325 (913) 780-6987.

COMMUNICATIONS: CTAF 133.0 UNICOM 122.95

® KANSAS CITY APP/DEP CON 118.9

TOWER 133.0 (1200-0400Z1) GND CON 124.3


CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc MCI Apch at 118.90.

AIRSPACE: CLASS D svc 1200-0400Z‡; other times CLASS G.


```
RADIO AIDS TO NAVIGATION: NOTAM FILE MCI.
```

KANSAS CITY (H) (H) VORTACW 113.25 MCI Chan 79(Y) N39°17.12' W94°44.22' 190° 28.2 NM to fld. 1017/5E. ILS/DME 110.9 I-IXD Chan 46 Rwy 36. Class IT.

4 SE UTC-6(-5DT) N38°50.86' W94°44.26'







KANSAS CITY L-10J. A IAP, AD

JOHNSON CO EXEC (OJC)(KOJC)

1.1% up N

UNICOM 122.95

® KANSAS CITY APP/DEP CON 118.9

1096 B TPA—See Remarks NOTAM FILE OJC

RWY 18: PAPI(P4R)-GA 3.0° TCH 40'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 18-36: H4097X75 (CONC) S-28 PCR 90 R/D/W/T MIRL

RWY 18: TORA-4097 TODA-4097 ASDA-4097 LDA-4097

RWY 36: TORA-4097 TODA-4097 ASDA-4097 LDA-4097

ACTIVATE MIRL Rwy 18-36, MALSR Rwy 36, twy lgts and wind

SERVICE: S4 FUEL 100LL, JET A 0X 2, 4 LGT When twr clsd

RWY 36: MALSR. VASI(V2L)-GA 3.0° TCH 40'. Trees.