

## HARLAN CO LAKE SPB (See ALMA on page 288)

**HARTINGTON MUNI/BUD BECKER FLD** (ØB4) 2 SE UTC-6(-5DT) N42°36.19' W97°15.21'OMAHA  
L-12H  
IAP

1388 B NOTAM FILE OLU

RWY 13-31: H3950X60 (CONC) MIRL 0.3% up SE

RWY 13: PAPI(P2L)—GA 3.5° TCH 46'.

RWY 31: PAPI(P2L)—GA 3.25° TCH 40'. Thld dsplcd 400'.

RWY 03-21: 2150X125 (TURF) 0.6% up SW

SERVICE: S4 FUEL 100LL LGT ACTIVATE MIRL Rwy 13-31, PAPI Rwy 13 and Rwy 31—CTAF.

AIRPORT REMARKS: Attended continuously. For fuel call 402-254-7316 or 402-841-0659. Rwy 03-21 not plowed during winter months.

AIRPORT MANAGER: 402-841-0659

COMMUNICATIONS: CTAF 122.9

Ⓡ MINNEAPOLIS CENTER APP/DEP CON 125.025

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.


RADIO AIDS TO NAVIGATION: NOTAM FILE YKN.

YANKTON (L) DME 111.4 YKN Chan 51 N42°55.10'

W97°23.10' 163° 19.8 NM to fld. 1301.

DME unusable:

249°-264° byd 24 NM blo 2,800'

**HARVARD STATE** (Ø8K) 2 NE UTC-6(-5DT) N40°39.08' W98°04.79'OMAHA  
L-101  
IAP

1815 B NOTAM FILE OLU

RWY 14-32: 3873X150 (TURF)

RWY 17-35: H3722X60 (ASPH) MIRL

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. Amgr lctd offsite; call for assistance.

100LL fuel avbl, ctc amgr for fuel; cash or ck only.

AIRPORT MANAGER: 402-266-1890

COMMUNICATIONS: CTAF 122.9

Ⓡ MINNEAPOLIS CENTER APP/DEP CON 119.4

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE HSI.

HASTINGS (L) DME 108.8 HSI Chan 25 N40°36.27'

W98°25.78' 080° 16.2 NM to fld. 1957.

