

MONTAUK (MTP)(KMTP) 3 NE UTC-5(-4DT) N41°04.60' W71°55.23'

7 NOTAM FILE MTP

RWY 06-24: H3246X75 (ASPH) MIRL

RWY 06: PAPI(P2R)—GA 3.83° TCH 45'. Thld dsplcd 302'. Trees.

RWY 24: PAPI(P2L)—GA 4.0° TCH 24'. Thld dsplcd 668'. Hill. Rgt tfc.

SERVICE: LGT ACTVT MIRL and PAPI Rwy 06-24—121.7. PAPI Rwy 06 temporarily OTS.

NOISE: Noise abatement, Rwy 24 dep, right turn ASAP.

AIRPORT REMARKS: Attended 15 Apr-Oct dalgt hrs. Deer on or invof aprt. PPR hel opns SS-SR; call amgr 631-668-3738. PPR jet acct; call amgr 631-668-3738. Helicopters call for prior permission to land on ramp area. No touch and goes Rwy 06-24. Rwy 06 18' brush along rwy edge 90' left, 30' pole 400' from thld 79' left, 31' pole 216' from rwy thld 233' right. Rwy 06, 26' tree 382' from thld 21' left, 25'-32' trees 180'-255' from thld 60'-90' left, 11'-17' trees 225'-270' from thld 4'-95' right. Rwy 24, 21' brush along rwy edge 87' rgt. Ldg fee.

AIRPORT MANAGER: 631-609-0932

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **NEW YORK APP CON** 125.975

Ⓡ **PROVIDENCE DEP CON** 125.75 (Sun-Fri 1030-0530Z‡, Sat 1030-0500Z‡) other times ctc

Ⓡ **BOSTON CENTER DEP CON** 124.85

CLEARANCE DELIVERY PHONE: For CD ctc Providence Apch at 401-738-8945, when Apch clsd ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE HTO.

HAMPTON (H) (H) VORTACW 113.6 HTO Chan 83 N40°55.14' W72°19.00' 075° 20.3 NM to fld. 22/13W.

DME unusable:

280°-325° byd 35 NM blo 1,700'

326°-355° byd 30 NM blo 2,000'

TACAN AZIMUTH unusable:

280°-325° byd 35 NM blo 1,700'

326°-355° byd 30 NM blo 2,000'

VOR unusable:

010°-240°

270°-332°

NEW YORK

COPTER

L-33C

IAP

