

LYNDONVILLE

CALEDONIA CO (CDA)(KCDA) 3 N UTC-5(-4DT) N44°34.15' W72°01.08'

1188 B TPA-2200(1012) NOTAM FILE BTV

RWY 02-20: H3302X60 (ASPH) S-12.5 MIRL 0.3% up N

RWY 02: REIL. Trees.

RWY 20: Trees.

SERVICE: LGT ACTVT REIL Rwy 02; MIRL Rwy 02-20-CTAF. ACTIVATE arpt rotating bcn-CTAF.

AIRPORT REMARKS: Attended Jan-Dec Mon-Fri 1200-2030Z±. Deer and wildlife on and invof arpt. Bald eagles roosting invof compost opn located 600' E of Rwy 20 thr year-around. Rwy conditions may not be monitored or reported when the arpt is unattended. Rising terrain 600' from thld of Rwy 02. Rwy 02-20 pavement has numerous sealed, large diameter transverse cracks. For emergency acft maintenance call 802-334-5001. Bring own rope tiedowns.

AIRPORT MANAGER: 802-279-9746

WEATHER DATA SOURCES: AWOS-3 119.275 (802) 626-4532.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **BOSTON CENTER APP/DEP CON** 135.7

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE MPV.

MONTPELIER (VL) (DH) VORW/DME 116.9 MPV Chan 116

N44°05.13' W72°26.96' 048° 34.5 NM to fld. 2086/16W.

VOR unusable:

010°-020° byd 25 NM blo 7,500'

015°-031° byd 40 NM

032°-042° byd 40 NM blo 5,000'

032°-042° byd 65 NM

043°-060° byd 40 NM

043°-070° byd 40 NM blo 9,100'

045°-060° byd 24 NM blo 8,500'

170°-182° byd 40 NM

210°-275° byd 40 NM

DME unusable:

043°-070° byd 40 NM

045°-060° byd 24 NM blo 8,500'

MONTREAL

L-32H

IAP

