

CONNER**WEST FORK LODGE** (4U7) 5 SW UTC-7(-6DT) N45°51.74' W114°13.07'

GREAT FALLS

4249 NOTAM FILE GTF

RWY 02-20: 2600X65 (TURF-GRVL) 0.7% up S**RWY 02:** Road.**RWY 20:** Road.

AIRPORT REMARKS: Unattended. Livestock, birds and wildlife invof arpt. No sn plowing in winter. Rwy 02-20 ocnl grvl down cntr of rwy-sml dip 600 ft fm Rwy 20 end. Steep terrain surrounding arpt. Trees and structures in transitional sfc full length both sides of ry. Rwy 02 +70 ft trees 600 ft fm rwy end & mtn 2700 ft fm thld; Rwy 20 +135 ft tree 80 ft right & 120 ft fm rwy end; +115 ft trees beginning 91 ft right pentg apch sfc.

AIRPORT MANAGER: (831) 884-3602**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**CONRAD** (SØ1) 1 W UTC-7(-6DT) N48°10.10' W111°58.59'

GREAT FALLS

3548 B NOTAM FILE GTF

L-13C

RWY 06-24: H4602X75 (ASPH) S-12.5 MIRL 0.4% up SW

IAP

RWY 06: PAPI(P2L)—GA 3.0° TCH 45'. P-line.**RWY 24:** REIL. PAPI(P2L)—GA 3.0° TCH 27'.**RWY 15-33:** 2800X100 (TURF) 0.4% up SE**SERVICE:** FUEL 100LL LGT ACTVT REIL Rwy 24; PAPI Rwy 24; MIRL Rwy 06-24—CTAF.**AIRPORT REMARKS:** Unattended. 100LL 24/7 self svc. Twys have reflectors.

Rwy 06-24 has uneven sfc, cracks and rprs. Rwy 06 faded flaking paint. Rwy 24 faded flaking paint.

AIRPORT MANAGER: (406) 450-1620**COMMUNICATIONS:** CTAF/AUNICOM 122.8**CUT BANK RCO** 122.2 (GREAT FALLS RADIO)Ⓡ **SALT LAKE CENTER APP/DEP CON** 133.4**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CTB.**CUT BANK (VL) (DH) VORW/DME** 113.35 CTB Chan 80(Y)

N48°33.90' W112°20.60' 131° 28.0 NM to fld.
3791/17E.

VOR unusable:

049°-053° byd 40 NM
061°-073° byd 40 NM
079°-090° byd 40 NM
125°-130° byd 40 NM
143°-149° byd 40 NM
167°-177° byd 40 NM blo 9,000'
167°-177° byd 54 NM
178°-190° byd 40 NM
191°-201° byd 40 NM blo 12,000'
191°-201° byd 53 NM
202°-260° byd 40 NM
271°-282° byd 40 NM

