

## LAMAR

**SOUTHEAST COLORADO RGNL** (LAA)(KLA) 3 SW UTC-7(-6DT) N38°04.18' W102°41.31'

WICHITA  
H-5A, L-10G  
IAP

3705 B NOTAM FILE LAA MON Airport

**RWY 18-36:** H6304X100 (CONC-GRVD) S-45, D-55, 2D-100

PCN 12 R/B/W/U MIRL 0.4% up S

**RWY 18:** REIL. VASI(V4L)—GA 3.0° TCH 45'. Road.

**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 44'. Hill.

**RWY 08-26:** H5001X60 (ASPH-AFSC) S-35, D-50, 2D-95 MIRL

**RWY 08:** REIL. PAPI(P2L)—GA 3.0° TCH 29'. Road.

**RWY 26:** REIL. PAPI(P2L)—GA 3.0° TCH 30'.

**SERVICE:** S4 FUEL 100LL, JET A OX 2, 4 LGT ACTVT and incr intst  
REIL Rwy 08 and 26, Rwy 18 and 36; PAPI Rwy 08 and 26, Rwy 36;  
VASI Rwy 18; MIRL Rwy 08-26, 18-36; twy lgts—CTAF. All lgts  
preset med intst.

**AIRPORT REMARKS:** Attended 1500-0000Z±. For svc after hrs phone  
719-336-7701. 100LL avbl H24 self svc. Be alert; intensive USAF  
student training in vicinity Colorado Springs and Pueblo Colorado.  
Tower 500' AGL 4.5 mile SE unlighted. NOTE: See Special  
Notices—Aerobatic Operations in Colorado. USAF 306 FTG Flight  
Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

**AIRPORT MANAGER:** 719-336-2002

**WEATHER DATA SOURCES:** ASOS 135.625 (719) 336-3854.


**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ DENVER CENTER APP/DEP CON 133.4

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAA.

LAMAR (VH) (DH) VORW/DME 116.9 LAA Chan 116 N38°11.83' W102°41.25' 168° 7.6 NM to fld. 3944/12E.



## LAS ANIMAS

**CITY OF LAS ANIMAS — BENT CO** (7V9) 1 S UTC-7(-6DT) N38°03.24' W103°14.31'

WICHITA  
L-10F

3915 NOTAM FILE DEN

**RWY 08-26:** H3870X40 (ASPH) S-5 HIRL 0.4% up W

**RWY 08:** REIL. Tree.

**RWY 26:** REIL. Road.

**SERVICE:** LGT Actvt HIRL Rwy 08-26—CTAF. Med intst 5 clicks, high intst 7 clicks. Rwy 08 and 26 REILS OTS.

**AIRPORT REMARKS:** Unattended. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Rwy  
26 has +30' poles 105' from thld 210' left of extd rwy centerline. Rwy 08-26 has trees growing 50+ ft fm either side  
of rwy cntrln. Thld lgts NSTD; three lgts each end. Thld lgts OTS indef. Rwy 08 thld lgts 23' from thld. Rwy 26 thld lgts  
12' from thld. Rwy 08 has +4' fence 275' from thld obstruction, has -3' ditch 35' from rwy end on both sides. Rwy  
08-26 numbers smaller than standard. Rwy 08 thld markings worn and unrdbl. See Special Notices—USAF 306 FTG  
Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

**AIRPORT MANAGER:** 719-662-1225

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAA.

LAMAR (VH) (DH) VORW/DME 116.9 LAA Chan 116 N38°11.83' W102°41.25' 240° 27.5 NM to fld. 3944/12E.

**LEACH** (See CENTER on page 328)