

ILS RWY 36C (CAT II & III)
CHARLOTTE/DOUGLAS INTL (CLT)

MISSED APPROACH: Climb to 3000 on CLT
VOR/DME R-001 to TOMME/CLT 15.4 DME
and hold.

T Simultaneous approach authorized.
DQG ILS LLZ Rwy 36C unusable for rollout guidance.

CLNC DEL	
127.15	
348.6	

[illegible]

[illegible]

ELEV 748	D	TDZE 707
----------	----------	----------

HIRL all Rwy's
REIL Rwy's 18L and 23
TDZ/CL Rwy's 18R, 36L, 36C and 36R

35°13'N-80°57'W

CHARLOTTE/DOUGLAS INTL (CLT)

35°13'N-80°57'W ILS RWY 36C (CAT II & III)

SE-2, 20 MAR 2025 to 17 APR 2025