

MARYSVILLE, CALIFORNIA

HI-TACAN Z RWY 33

TACAN BAB Chan 23	APCH CRS 317°	Rwy ldg 12,001 TDZE 105 Arpt Elev 113
----------------------	------------------	---

- (USAF)


BEALE AFB (KBAB)

T * When ALS inop, increase CAT CDE vis to 1 1/4 miles.
** Circling not authorized NE of Rwy 15-33.

ALSF-1

MISSED APPROACH: Climb to 3600, intercept BAB
TACAN R-326 to HAPAK and hold.

ATIS★ 124.55 273.5	NORCAL APP CON 125.4 259.1	TOWER★ 119.4 284.75	GND CON 121.6 257.75
----------------------------------	--	-----------------------------------	------------------------------------



MARYSVILLE, CALIFORNIA

39°08'N - 121°26'W

BEALE AFB (KBAB)

Amdt 6 25JAN24

HI-TACAN Z RWY 33