

**HARBOR SPRINGS** (MGN)(KMG) 3 E UTC-5(-4DT) N45°25.53' W84°54.81'

LAKE HURON

686 B NOTAM FILE MGN

L-31B

RWY 10-28: H4149X75 (ASPH) S-22, D-30 MIRL

IAP

RWY 10: PAPI(P4R)—GA 3.5° TCH 28'. Thld dsplcd 437'. Tree.

RWY 28: PAPI(P4L)—GA 4.0° TCH 35'. Thld dsplcd 444'. Pole.

**SERVICE:** FUEL 100LL, JET A+ LGT Actvt MIRL Rwy 10-28—CTAF.  
PAPI Rwy 10 and 28 opr consly. Rwy 28 PAPI unusable byd 2° left of centerline.

**NOISE:** Noise abatement procedures; no turbojet/turbofan acft depts frm 0400-1200Z±, no low flight ovr surrounding community, all acft depg to the W turn S ovr the water as soon as practical.

**AIRPORT REMARKS:** Attended 1300-dusk. Parachute Jumping. Birds and deer on and invof arpt. Rwy 10 apch area has two 70' lgtd obstruction poles 170' left of cntrln; +75' trees on N side. Rwy 28 apch area has lgtd obstruction poles, 165' left and 220' right of cntrln; 80' trees adj. Landing fee waived with minimum fuel purchase.

AIRPORT MANAGER: 231-206-9333

**WEATHER DATA SOURCES:** AWOS-3P 119.925 (231) 347-5231. Wind spd & drctn unrel btn 260°-280°.

COMMUNICATIONS: CTAF/UNICOM 122.8

® MINNEAPOLIS CENTER APP/DEP CON 134.6

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.


RADIO AIDS TO NAVIGATION: NOTAM FILE PLN.

PELLSTON (L) (L) VORTACW 111.8 PLN Chan 55 N45°37.84' W84°39.85' 227° 16.2 NM to fld. 836/6W.

VOR unusable:

301°-339°

GCP has azm only, no DME at GCP

**HARRIETTA****EAGLES LANDING** (4Y9) 3 W UTC-5(-4DT) N44°18.47' W85°46.30'

GREEN BAY

993 NOTAM FILE LAN

RWY 08-26: 2200X100 (TURF) 0.8% up E

RWY 08: Trees.

RWY 26: Trees.

**AIRPORT REMARKS:** Unattended. No snow removal. Lrg depression east of Rwy 26. Rwy 08-26 mkd with 3' yellow cones. 60' trees both sides of rwy 100' from rwy cntrln.

AIRPORT MANAGER: 586-944-7101

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

**HARRISON****CLARE CO** (8ØD) 2 N UTC-5(-4DT) N44°03.14' W84°48.79'

LAKE HURON

1142 B NOTAM FILE LAN

RWY 18-36: H2978X50 (ASPH) LIRL(NSTD)

RWY 18: Thld dsplcd 465'. Tree.

RWY 36: Thld dsplcd 1160'. Tree.

RWY 09-27: 2403X100 (TURF)

RWY 09: Thld dsplcd 1196'. Tree.

RWY 27: Thld dsplcd 837'. Tree.

**SERVICE:** LGT Actvt NSTD LIRL Rwy 18-36—CTAF. Rwy 18-36 NSTD LIRL due to improper color and lctn.

**AIRPORT REMARKS:** Unattended. Deer & lrg birds on & invof arpt. Rwy 09-27 CLOSED Nov-Mar and when snow covd exc for ski equipped acft. Rwy 09 and 27 dthr mkd with 3 ft yellow cones. Rwy 09-27 intrmt patches of misg turf thrut full len & wid.

AIRPORT MANAGER: 989-862-5333

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.