

ADIRONDACK RGNL (See SARANAC LAKE on page 242)

AIRHAVEN (See STAATSBURG on page 249)

AIRLANE ENTERPRISES (See CLAY on page 196)

AKRON/JESSON FLD (9G3) 1 E UTC-5(-4DT) N43°01.27' W78°28.96'

840 B NOTAM FILE BUF

RWY 07-25: H3268X75 (ASPH) S-8 MIRL 0.3% up NE

RWY 07: PAPI(P2L)—GA 4.0° TCH 54'. Trees.

RWY 25: REIL. PAPI(P2L)—GA 4.0° TCH 55'. Trees.

RWY 11-29: 1955X50 (TURF)

RWY 11: Trees.

RWY 29: Trees.

SERVICE: FUEL 100LL LGT ACTVT PAPI Rwy 07 & 25, REIL Rwy 25; MIRL Rwy 07-25—CTAF. Rwy 07 VGSI unusbl byd 7 degs right of cntrln.

NOISE: Rwy 25 noise abatement—mntn rwy hdg til 3/4 miles byd dep end Rwy 25 bfr turning.

AIRPORT REMARKS: Unattended. For atndtc call 716-864-5004. 100LL fuel 24 hr self svc. Call arpt mgr. Rwy 11-29 CLOSED indefly. Full publ len not avbl. Parallel twy lighted and 35' wide.

AIRPORT MANAGER: 716-542-4607

COMMUNICATIONS: CTAF/UNICOM 122.725

® **BUFFALO APP/DEP CON** 126.15

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE BUF.

BUFFALO (DH) DME 116.4 BUF Chan 111 N42°55.74' W78°38.78' 052° 9.1 NM to fld, 730.

DME unusable:

051°-085° byd 25 NM blo 4,500'

301°-050° byd 25 NM blo 3,500'

DETROIT

L-31E

IAP

