

**RICHLANDS**

**TAZEWELL CO** (JFZ)(KJFZ) 2 S UTC-5(-4DT) N37°03.82' W81°47.90'

CINCINNATI  
L-26H  
IAF

2653 B NOTAM FILE JFZ

**RWY 07-25:** H4299X75 (ASPH) S-12.5, D-18 MIRL

**RWY 07:** REIL. PAPI(P2L)—GA 3.5° TCH 47'. Trees.

**RWY 25:** REIL. PAPI(P2L)—GA 3.5° TCH 47'. Tree.

**SERVICE:** FUEL 100LL, JET A+ LGT MIRL Rwy 07-25 preset low instst.

To increase instst and ACTVT REIL Rwy 07 and 25; PAPI Rwy 07-25—CTAF.

**AIRPORT REMARKS:** Attended Mon-Sat 1300-2200Z±. Unattended New Year's Day, Thanksgiving, and Christmas. For Sunday svc call arpt during regular business hrs to arrange. Rwy 07 markings covered by algae. Rwy 25 markings covered by algae.

**AIRPORT MANAGER:** 276-963-4509

**WEATHER DATA SOURCES:** AWOS-3 118.075 (276) 596-9927.

**COMMUNICATIONS:** CTAF/UNICOM 123.05

Ⓡ ATLANTA CENTER APP/DEP CON 127.85

GCO 135.075 (thru ZTL clnc del and DCA RADIO) - inop.

**CLEARANCE DELIVERY PHONE:** For CD if una via GCO ctc Atlanta ARTCC at 770-210-7692.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.

**GLADE SPRING (L) (L) VOR/DME** 115.55 GZG Chan 102(Y)

N36°49.51' W82°04.74' 045° 19.7 NM to fld. 4200/2W.


VOR unusable:

010°-095°

115°-120° byd 20 NM blo 10,000'

351°-004° byd 15 NM blo 8,000'

**LOC/DME** 109.75 I-JFZ Chan 34(Y) Rwy 25.



**RICHMOND**

**RICHMOND EXEC/CHESTERFIELD CO** (FCI)(KFCI) 4 SW UTC-5(-4DT) N37°24.39'

WASHINGTON  
H-10H, 121, L-36H  
IAF

W77°31.49'

236 B TPA—See Remarks LRA NOTAM FILE DCA

**RWY 15-33:** H5500X100 (ASPH-GRVD) S-60, D-80 HIRL

0.7% up NW

**RWY 15:** REIL. PAPI(P4L)—GA 3.0° TCH 43'. Trees.

**RWY 33:** MALSR. PAPI(P4L)—GA 3.0° TCH 50'. Trees.

**SERVICE:** S4 FUEL 100LL, JET A OX 3 LGT HIRL Rwy 15-33 preset low instst; incr instst and actvt MALSR Rwy 33 and REIL Rwy 15—CTAF.

**NOISE:** Noise sensitive area north of arpt. No wind voluntary use of Rwy 15 preferred.

**AIRPORT REMARKS:** Attended 1200-0300Z±. Fuel aft hrs call 804-271-7793 or 844-435-9732 btn 0300-1200Z±. 400' twr 5 NM north of arpt. Actn on ILS apch to Richmond Intl crossing over arpt. Med-flight: irregular departure pattern. Helicopter parking adj to Twy C. TPA—1236(1000) single engine, 1736(1500) multi-engine. ARFF eqpt and trained personnel avbl at arpt.

**AIRPORT MANAGER:** 804-768-7722

**WEATHER DATA SOURCES:** AWOS-3PT 128.625 (804) 271-8426.

**COMMUNICATIONS:** CTAF/UNICOM 123.05

Ⓡ POTOMAC APP/DEP CON 126.75 118.2

CLNC DEL 124.6

**CLEARANCE DELIVERY PHONE:** For CD ctc Potomac Apch at 866-640-4124.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.

**FLAT ROCK (H) (H) VORTACW** 113.3 FAK Chan 80 N37°31.71' W77°49.69' 123° 16.2 NM to fld. 460/6W.

TACAN 338 radial unusable

VOR unusable:

111°-168°

169°-204° blo 5,000'

274°-337° blo 4,000'

274°-337° byd 33 NM

**ILS/DME** 108.3 I-CFU Chan 20 Rwy 33. Class IA. LOC/DME unmonitored when arpt unatndd.

