

FESSENDEN-STREIBEL MUNI	(D24)	3 NW	UTC-6(-5DT)	N47°39.58' W99°39.66'	TWIN CITIES
1619	NOTAM FILE GFK				
RWY 08-26:	2940X120 (TURF)	LIRL			
RWY 08:	Road.				
RWY 26:	Trees.				
SERVICE:	LGT ACTIVATE LIRL Rwy 08-26—CTAF.				
AIRPORT REMARKS:	Unattended. Waterfowl and deer on or inovf arpt during migratory season. Dalgt cone markers at rwy thlds, and stopway areas. Rwy 08 has lgtd 300' stopway and Rwy 26 has 550' lgtd stopway. No snow removal avbl—confirm condition prior to use Oct–Apr.				
AIRPORT MANAGER:	701-653-5069				
COMMUNICATIONS:	CTAF 122.9				
CLEARANCE DELIVERY PHONE:	For CD ctc Minneapolis ARTCC at 651-463-5588.				

FORT YATES

STANDING ROCK	(Y27)	1 S	UTC-6(-5DT)	N46°04.01' W100°37.97'	TWIN CITIES
1634	B	NOTAM FILE GFK			L-14F
RWY 14-32:	H3699X60 (ASPH)	S-11.5	MIRL		
RWY 14:	PAPI(P2L)—GA 3.0° TCH 30'.				
RWY 32:	PAPI(P2L)—GA 3.0° TCH 30'. Fence.				
RUNWAY DECLARED DISTANCE INFORMATION					
RWY 14:	TORA-3699 TODA-3699 ASDA-3699 LDA-3699				
RWY 32:	TORA-3699 TODA-3699 ASDA-3699 LDA-3699				
SERVICE:	LGT ACTVT PAPI Rwy 14 and 32—CTAF. MIRL Rwy 14-32 opr consly dusk-0600Z‡; after 0600Z‡ ACTVT—CTAF.				
AIRPORT REMARKS:	Unattended. Birds & waterfowl on & inovf arpt. Cfm snow removal Oct–Apr; call 701-854-8611; 701-455-1811; 701-854-8622. Gate code protected – local zip code.				
AIRPORT MANAGER:	701-301-7463				
COMMUNICATIONS:	CTAF 122.9				
CLEARANCE DELIVERY PHONE:	For CD ctc Minneapolis ARTCC at 651-463-5588.				
RADIO AIDS TO NAVIGATION:	NOTAM FILE BIS.				
BISMARCK (VL) (DH) VORW/DME	115.65	BIS	Chan 103(Y)	N46°45.71' W100°39.92'	166° 41.7 NM to fld.
	1854/12E.				

GACKLE MUNI	(9G9)	1 SW	UTC-6(-5DT)	N46°37.29' W99°09.87'	TWIN CITIES
1904	NOTAM FILE GFK				
RWY 08-26:	1620X40 (TURF)	0.4% up W			
RWY 17-35:	1150X40 (TURF)	0.5% up S			
AIRPORT REMARKS:	Unattended. Arpt CLOSED winter due to lack of snow removal. Birds on and inovf arpt. Pilots at end of rwy cannot see acft at opposite end of rwy due to rwy gradient. +5' hill 60' R of AER. Rwy 17-35 and Rwy 08-26 turf surface rolling; grass clumpy and possible animal holes. Be alert, Rwy 08 first 200' rise at 5% slope. Ctn lake shore 20' fm Rwy 8 and 26 N edge near rwy midpt.				
AIRPORT MANAGER:	701-485-3241				
COMMUNICATIONS:	CTAF 122.9				
CLEARANCE DELIVERY PHONE:	For CD ctc Minneapolis ARTCC at 651-463-5588.				

GARRISON DAM RECREATIONAL AIRPARK (See RIVERDALE on page 359)

GARRISON MUNI	(D05)	1 W	UTC-6(-5DT)	N47°39.36' W101°26.21'	BILLINGS
1937	B	NOTAM FILE GFK			L-14F
RWY 13-31:	H3699X60 (ASPH)	S-12.5	MIRL	0.8% up NW	IAP
RWY 13:	PAPI(P2L)—GA 3.0° TCH 29'.	Road.			
RWY 31:	PAPI(P2L)—GA 3.0° TCH 29'.				
RWY 03-21:	2618X120 (TURF)				
RWY 03:	Road.				
RWY 21:	Trees.				
SERVICE:	FUEL 100LL	LGT ACTIVATE PAPI Rwy 13 and Rwy 31; MIRL Rwy 13-31—CTAF.			
AIRPORT REMARKS:	Unattended. 24 hr self svc credit card fuel avbl. Wildlife and birds on and inovf arpt. Confirm snow removal ctc arpt manager or City Hall 701-463-2600. Rwy 03-21 CLSD winter months due to lack of snow removal.				
AIRPORT MANAGER:	(701) 301-1055				
COMMUNICATIONS:	CTAF 122.9				
⑧ MINNEAPOLIS CENTER APP/DEP CON	127.6				
CLEARANCE DELIVERY PHONE:	For CD ctc Minneapolis ARTCC at 651-463-5588.				
RADIO AIDS TO NAVIGATION:	NOTAM FILE BIS.				
BISMARCK (VL) (DH) VORW/DME	115.65	BIS	Chan 103(Y)	N46°45.71' W100°39.92'	318° 62.3 NM to fld.
	1854/12E.				