

**MINNEAPOLIS CITY CO** (45K) 2 SW UTC-6(-5DT) N39°05.66' W97°43.26'

1246 NOTAM FILE ICT

**RWY 16-34:** H3970X20 (ASPH)

**RWY 16:** Trees.

**RWY 34:** Trees.

**AIRPORT REMARKS:** Attended Apr–Nov dawn–dusk. Arpt opr daylight hrs only.

Deer on and invof arpt.

**AIRPORT MANAGER:** 785-392-3300

**COMMUNICATIONS:** CTAF 122.9

**⑧ KANSAS CITY CENTER APP/DEP CON** 134.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at

913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SLN.

**SALINA (VH) (H) VORTACW** 117.1 SLN Chan 118 N38°55.51'

W97°37.28' 328° 11.2 NM to fld. 1316/7E.

VOR unusable:

017°-026° byd 40 NM


315°-016° byd 15 NM blo 6,000'

DME unusable:

300°-042° byd 15 NM blo 6,000'

**WICHITA**

L-10I



## MOLINE

**ELK CO** (2K6) 3 NE UTC-6(-5DT) N37°22.86' W96°16.27'

**KANSAS CITY**

1063 NOTAM FILE ICT

**RWY 18-36:** H2510X40 (ASPH) 0.4% up N

**RWY 36:** Pole.

**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Rwy 18–36 has centerline marking only. Rwy 36 the poles that constitute the controlling obstruction on the right are not visibly marked or lgtd.

**AIRPORT MANAGER:** 620-374-3597

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

**KANSAS CITY**

L-15C

**MONTEZUMA MUNI** (K17) 2 SW UTC-6(-5DT) N37°35.14' W100°28.21'

**WICHITA**

L-15C

2780 NOTAM FILE ICT

**RWY 17-35:** H4000X60 (ASPH) MIRL

**RWY 17:** Thld dispclcd 700'. Road.

**RWY 35:** Road.

**SERVICE:** LGT ACTIVATE MIRL Rwy 17–35—CTAF.

**AIRPORT REMARKS:** Unattended. +6 ft irrigation engine/pump located on Rwy 17–35 W edge near windsock.

**AIRPORT MANAGER:** 620-846-0550

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

**MORITZ MEML** (See BELOIT on page 88)