

CHAMBERS FLD (See NORFOLK NS (CHAMBERS FLD) on page 372)**CHARLOTTESVILLE–ALBEMARLE** (CHO)(KCHO) 7 N UTC-5(-4DT) N38°08.38'

W78°27.14'

640 B ARFF Index—See Remarks NOTAM FILE CHO MON Airport

RWY 03-21: H6801X150 (ASPH-GRVD) S-89, D-114, 2S-175,
2D-171 PCR 360 F/D/X/T HIRL 0.3% up SW**RWY 03:** MALSR. PAPI(P4L)—GA 3.0° TCH 53'.**RWY 21:** REIL. PAPI(P4R)—GA 3.0° TCH 50'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 03:** TORA-6801 TODA-6801 ASDA-6801 LDA-6801**RWY 21:** TORA-6801 TODA-6801 ASDA-6801 LDA-6801**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** When ATCT clsd HIRL Rwy
03-21, and twy lights preset low intst. To actvt and increase intst
MALSR Rwy 03; REIL Rwy 21; HIRL Rwy 03-21 and twy
lights—CTAF. Rwy 21 VGSJ unusbl byd 6.5 deg L of RCL.**AIRPORT REMARKS:** Attended continuously. Deer and birds on and invof arpt.For acft svcs ctc 126.925. Class I, ARFF Index B. PPR 24 hrs for
unskd air carrier ops with more than 30 psgr seats, 24 hr PPR for all
fixed wing mil aircraft RON, call arpt manager 434-981-4152.

Wheeled helicopters are requested to ground taxi when transiting arpt.

Ldg fee only for acft over 7000 lbs.

AIRPORT MANAGER: 434-973-8342**WEATHER DATA SOURCES:** ASOS (434) 975-0110**COMMUNICATIONS:** CTAF 124.5 ATIS 118.425 UNICOM 122.95® **POTOMAC APP/DEP CON** 132.85**APP/DEP CON** 120.525**TOWER** 124.5 (1100-0400Z) **GND CON** 121.9**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Potomac Apch at 866-640-4124.**AIRSPACE:** CLASS D svc 1100-0400Z; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**GORDONSVILLE (VH) (H) VORTAC** 115.6 GVE Chan 103 N38°00.82' W78°09.18' 304° 16.1 NM to fld. 383/6W.

TACAN AZIMUTH unusable:

250°-260° byd 25 NM blo 7,000'

VOR unusable:

005°-050° byd 40 NM

180°-207° byd 40 NM

208°-218° byd 40 NM blo 3,000'

208°-218° byd 50 NM

219°-225° byd 40 NM

260°-301° byd 40 NM

302°-312° byd 40 NM blo 9,000'

302°-312° byd 65 NM

313°-331° byd 40 NM

332°-342° byd 40 NM blo 6,100'

332°-342° byd 46 NM

343°-360° byd 40 NM

ILS/DME 111.7 I-CHO Chan 54 Rwy 03. Class IA. ILS unmonitored when ATCT closed.**WASHINGTON**

H-10H, 121, L-261, 36H

IAP, AD

