

FRANKLIN RGNL (FKN)(KFKN) 2 NE UTC-5(-4DT) N36°42.02' W76°54.13'

WASHINGTON

40 B TPA—See Remarks NOTAM FILE FKN

L-35C, 36H

RWY 09-27: H4977X100 (ASPH-GRVD) MIRL

IAP

RWY 09: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

RWY 27: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** Actvt MIRL Rwy 09-27—CTAF.

Rwy 27 PAPI unusable byd 1 NM fm thr.

AIRPORT REMARKS: Attended 1300-2200Z†. Deer on and infov arpt.

Possible tfc from the Southampton Memorial Helipad 2 NM west of arpt. TPA—840(800) lgt acct, 1540(1500) hvy acct. Drainage ditches next to rwy & twys. Arpt FBO clsd Sat and Sun.

AIRPORT MANAGER: 757-562-8764

WEATHER DATA SOURCES: AWOS-3PT 124.675 (757) 562-8765.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **NORFOLK APP/DEP CON** 127.9

CLEARANCE DELIVERY PHONE: For CD ctc Norfolk Apch at 757-464-0757.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

HOPEWELL (VL) (H) VORTACW 114.35 HPW Chan 90(Y)

N37°19.73' W77°06.96' 171° 39.0 NM to fld. 70/6W.

VOR unusable:

052°-060° byd 40 NM

100°-105° byd 40 NM


150°-160° byd 40 NM

205°-220° blo 4,500'

225°-242° byd 30 NM blo 6,000'

295°-305° byd 40 NM

330°-345° byd 40 NM



FREDERICKSBURG

SHANNON (EZF)(KEZF) 2 S UTC-5(-4DT) N38°16.01' W77°26.95'

WASHINGTON

85 B NOTAM FILE EZF

L-29E, 34E, 36I, A

RWY 06-24: H2902X100 (ASPH) MIRL

IAP

RWY 06: PVASI(P SIL). Thld dspcd 132'. Railroad.

RWY 24: PVASI(P SIL). Thld dspcd 80'. Tree.

RWY 15-33: 1300X100 (TURF)

RWY 15: Brush.

SERVICE: S4 **FUEL** 100LL, JET A+ **LGT** ACTVT MIRL Rwy

06-24—CTAF. Rwy 06 PVASI OTS indefly.


AIRPORT REMARKS: Attended 1300-2200Z†. Unattended New Year's,

Easter, Independence, Thanksgiving and Christmas Days. Rwy 33 CLOSED daily SS-SR. 24 hr self-svc avbl, fuel truck avbl during opr hrs. Rwy 15 clsd to Indg. Rwy 33 clsd for tkof. Rwy 15-33 outlined with yellow cones. First 89 ft pavement Rwy 06 marked as unusbl.

Apchs to Rwy 06-24 will be made sufly high to cross Rt. 2 (Rwy 24) for the railroad tracks (Rwy 06) at or abv 135' MSL (50' AGL). Tran acct park on ramp NE side of trml. Req R/W acct not taxi next to trml.

AIRPORT MANAGER: 540-373-4431

WEATHER DATA SOURCES: AWOS-3 128.125 (540) 372-6794.



CONTINUED ON NEXT PAGE

