

CONWAY—HORRY CO (HYW)(KHYW) 3 W UTC-5(-4DT) N33°49.71' W79°07.33'

CHARLOTTE

35 B NOTAM FILE AND

L-241, 35A

RWY 04-22: H4401X75 (ASPH) S-12.5, D-20 MIRL

IAP

RWY 04: REIL. PAPI(P4R)—GA 3.35° TCH 48'. Tree.**RWY 22:** REIL. PAPI(P4L)—GA 3.0° TCH 43'. Tree.**SERVICE:** S4 **FUEL** 100LL, JET A, A+ **LGT** Actvt MIRL Rwy 04-22—CTAF.**AIRPORT REMARKS:** Attended 1400-2200Z†. Fuel 24 hrs credit card self svc avbl.**AIRPORT MANAGER:** 843-448-1580**WEATHER DATA SOURCES:** AWOS-3 119.525 (843) 397-8046.**COMMUNICATIONS:** CTAF/UNICOM 122.7® **MYRTLE BEACH APP/DEP CON** 127.4 (1100-0400Z†)**JACKSONVILLE CENTER APP/DEP CON** 134.375 (0400-1100Z†)**CLEARANCE DELIVERY PHONE:** For CD ctc Myrtle Beach Apch at 843-477-2727 or 843-477-2704, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CRE.**GRAND STRAND (VL) (H) VORTACW** 114.4 CRE Chan 91

N33°48.83' W78°43.47' 276° 19.9 NM to fld. 27/3W.

TACAN AZIMUTH unusable:

296°-335°

DME unusable:

296°-335°

VOR unusable:

000°-005° byd 40 NM

016°-020° byd 40 NM

040°-053° byd 40 NM blo 2,500'

040°-053° byd 47 NM

060°-085° byd 40 NM

130°-140° byd 40 NM


205°-222° byd 40 NM blo 7,000'

205°-222° byd 82 NM

292°-296° byd 40 NM

296°-308° byd 30NM blo 5,000'

330°-334° byd 40 NM

**DARLINGTON****BRANHAMS** (6J7) 3 SW UTC-5(-4DT) N34°16.89' W79°55.66'

CHARLOTTE

166 B NOTAM FILE AND

RWY 16-34: 3200X100 (TURF) LIRL**RWY 16:** VASI(V2L). Trees. Rgt t/c.**RWY 34:** VASI(V2L)—GA 4.0° TCH 45'. Road.**SERVICE:** S2 **LGT** Actvt VASI Rwy 16 and 34; LIRL Rwy 16-34—CTAF. Arpt rotating bcn OTS indefly.**AIRPORT REMARKS:** Unattended. On call 803-467-6941. Rwy 16-34 slightly bumpy in some areas. Rwy 16 has right traffic only.**AIRPORT MANAGER:** 843-307-0070**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Florence Apch at 843-665-0632, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.