

DEFUNIAK SPRINGS (54J) 2 W UTC-6(-5DT) N30°43.87' W86°09.23'

289 B NOTAM FILE GNV

NEW ORLEANS

L-21C, 22H

IAP

RWY 09-27: H4146X60 (ASPH) S-20 PCN 6 F/A/X/T MIRL**RWY 09:** PAPI(P2L)—GA 3.0° TCH 43'. Fence.**RWY 27:** PAPI(P2L)—GA 3.0° TCH 49'. Thld dsplcd 605'. Railroad.**RWY 18-36:** 2700X60 (DIRT) 0.5% up N**RWY 18:** Thld dsplcd 165'. P-line.**RWY 36:** Thld dsplcd 400'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A+ **OX3** **LGT** Actvt PAPI Rwy 09 and 27; MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z†. Fuel 24 hr credit card svc avbl. Trees obst ln of sight btn Rwy 09 and 36 and Rwy 27 and 36. Rwy 09 and 27 ln of sight obst due to Rwy 09 up slope. Rwy 18-36 white pvc pipe every 200 ft. Rwy safety area E of Rwy 18-36. Rwy 09 unlgtd fence and rd 160 ft S of cntrln penetrates apch sfc. Rwy 36 white reflectors every 200 ft.**AIRPORT MANAGER:** 850-892-2000**WEATHER DATA SOURCES:** AWOS-3P 118.725 (850) 892-0147.**COMMUNICATIONS:** CTAF/UNICOM 123.05® **EGLIN APP/DEP CON** 124.05**CLNC DEL IFR CLNC** ctc Eglin Rapcon 850-882-9151 prior to departure.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CEW.**CRESTVIEW (VH) (H) VORTACW** 115.9 CEW Chan 106 N30°49.57' W86°40.75' 099° 27.7 NM to fld. 255/3E.

VOR unusable:

005°-015° byd 40 NM

085°-095° byd 40 NM

155°-175° byd 40 NM

258°-268° byd 40 NM blo 3,100'

258°-268° byd 49 NM blo 18,000'

285°-305° byd 40 NM

306°-329°

340°-350° byd 40 NM blo 3,500'

340°-350° byd 64 NM

351°-355° byd 40 NM

