214 AI ASKA

SCAMMON BAY (SCM)(PACM) N61°50.67′ W165°34.43′ 0 N UTC-9(-8DT)

B NOTAM FILE SCM

RWY 11-29: 3001X75 (DIRT) MIRI

RWY 29: Brush. Rgt tfc.

LGT ACTVT MIRL Rwv 11-29-CTAF. SERVICE-

AIRPORT REMARKS: Unattended. Rwy condition unmnt, rcmd visual insp prior to use. Birds on rwy. Cold temperature airport. Altitude correction required at or below -20C. Road used to cross rwy to river, CAUTION: psbl gusty crosswind. Rwy 11-29 soft durg spring breakup, after rain and high tide. Rwy 11-29 edges soft and sloughing twd tundra, Road Xs rwy. Rwy 29 safety area soft and contains Irg rock; only 75 ft usbl. Wind indicators unreliable. Rwy 29 mkd with cones and reflective thr panels. Rwy 11 cones and thr panels, panels damaged or missing.

AIRPORT MANAGER: 907-543-2498 WEATHER DATA SOURCES: AWOS-3P 118.425 (907) 558-5501. (WX CAM)

COMMUNICATIONS: CTAF/UNICOM 123.0

R ANCHORAGE CENTER APP/DEP CON 124.5

RADIO AIDS TO NAVIGATION: NOTAM FILE HPB.

HOOPER BAY (H) (H) VORW/DME 115.2 HPB Chan 99 N61°30.86 W166°08.07′ 026° 25.5 NM to fld. 15/13E.

VOR unusable:

358°-013° byd 22 NM blo 3,500°

DME unusable:

358°-013° byd 22 NM blo 3,500′

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

SCOOTERS LANDING STRIP (See STERLING on page 228)

SCOTTS (See NORTH POLE on page 183)

SECLUDED LAKE (See TALKEETNA on page 231)

SELAWIK

ROLAND NORTON MEML AIRSTRIP (8AK3) PVT 12 S UTC-9(-8DT) N66°45.96′ W160°09.17′

NOME 1-41

NOME

L-41

IAP

RWY 02-20: 3000X70 (GRVL)

360 NOTAM FILE RWY 20: Mtn.

AIRPORT REMARKS: Unattended. Rwy slopes downhill at 3% toward west. Rwy condition not monitored; recommend visual inspection prior to landing. Rwys marked with red and white 55 gallon drums.

COMM/NAV/WEATHER REMARKS: For LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

SELAWIK (WLK)(PASK) 0 E UTC-9(-8DT) N66°36.01′ W159°59.15′

17 B NOTAM FILE WLK

RWY 04-22: 3002X60 (GRVL) MIRL

RWY 04: VASI(V4L)-GA 3.0° TCH 25'. Brush.

RWY 22: Brush.

RWY 09-27: 2659X60 (GRVL) MIRI

RWY 09: Brush.

RWY 27: PAPI(P4R)-GA 3.0° TCH 25'. Brush.

SERVICE: LGT ACTVT VASI Rwy 04; PAPI Rwy 27; MIRL Rwy 09-27 and Rwy 04-22, and rot bcn-CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmdd visual insp prior to use

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: AWOS-3P 135.65 (907) 484-2107. (WX CAM) COMMUNICATIONS: CTAF 122.7

SELAWIK RCO 122.5 (KOTZEBUE RADIO)

ANCHORAGE CENTER APP/DEP CON 119.2 263.0


RADIO AIDS TO NAVIGATION: NOTAM FILE WLK.

(H) (H) VORW/DME 114.2 WLK Chan 89 N66°35.97

W159°59.45' at fld. 11/16E.

COMM/NAV/WEATHER REMARKS: For LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll

free call to Fairbanks FSS dial 1-866-248-6516.



RETHEL

L-3B

IAP

