



LOC I-FJU 110.1	APP CRS 045°	Rwy Ldg TDZE 661 Apt Elev 680
---------------------------	------------------------	---

ILS RWY 4R (SA CAT I & II)
CHICAGO O'HARE INTL (ORD)

RADAR required for procedure entry.				MALSR 	MISSED APPROACH: Climb to 1200 then climbing right turn to 4000 on heading 060° and OBK VOR/DME R-134 to LAIRD INT/OBK 21.4 DME and hold.
-------------------------------------	--	--	--	--	---

D-ATIS 135.4 282.225	CHICAGO APP CON 119.0 292.125	O'HARE TOWER 120.75 348.0	124.125 GND CON 118.05 (TWR NORTH) 226.675 (TWR SOUTH) (ALL TWRs)	(TWR CENTER) 121.75 (OBND) 121.9 (BND)	CLNC DEL 121.6	CPDLC
--	--	-------------------------------------	---	--	--------------------------	-------



CATEGORY	A	B	C	D
S-ILS 4R	SA CAT I	RA 160/16	150	DA 811
S-ILS 4R	SA CAT II	RA 111/12	100	DA 761

SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

